

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009761/ANY3Q2**Date:** 27/12/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00055702201

**Claimant Vehicle
No :** GBJ6671Y**Insured Vehicle
No :** GX8851Z

Date of Loss: 23/09/2022

Nature of Claim: TP

Claim
No: SNM22D206819/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ6671Y**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2860102

Reg. Date: 11/07/2019 (Man. Year: 2019)

Chassis No: JTFAT35Y60K213686

Colour: Silver

Odometer: 160874 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: Farroad 6 mm

Rear Left Side: Farroad 6 mm

Front Right Side: Farroad 6 mm

Rear Right Side: Farroad 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,976.80	2,941.95	2,034.85	40.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,480.00	780.00	34.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,236.80	4,421.95	2,814.85	38.90
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	7,236.80	3,500.00	3,736.80	51.64
+ GST 7.00/7.00% (S\$)	506.58	245.00	261.58	51.64
Nett Amount (S\$)	7,743.38	3,745.00	3,998.38	51.64

INSPECTION

Date of Assignment: 03/10/2022

Date Inspected: 04/10/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ6671Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EXHAUST PIPE	Not Necessary	618.30 FL	*- FL
2	1		*REAR EXHAUST PIPE RUBBER MOUNTING	Not Necessary	61.10 FL	*- FL
3	2		*REAR NUMBER PLATE LAMP L/R	Cracked	121.40 FL	*121.40 FL
4	1		*REAR NUMBER PLATE PANEL	Bent	228.60 FL	*228.60 FL
5	1		*REAR NUMBER PLATE PANEL BRACKET	Bent	57.10 FL	*57.10 FL
6	1		*REAR SIDE RUBBER STOPPER BRACKET L/R	N/S Bent	197.20 FL	*98.60 FL
7	2		*REAR SIDE RUBBER STOPPER L/R	Not Necessary	86.20 FL	*- FL
8	1		*REAR TAILGATE	Dented	1,116.70 FL	*1,116.70 FL
9	1		*REAR TAILGATE DYNA STICKER	Necessary	61.20 FL	*61.20 FL
10	1		*REAR TAILGATE TOYOTA STICKER	Necessary	238.90 FL	*238.90 FL
11	1		*REAR TAILGATE FLIP LOCK HANDLE L/R	N/S Bent	278.00 FL	*139.00 FL
12	4		*REAR TAILGATE HINGES	Bent (2 PCS ONLY)	416.00 FL	*208.00 FL
13	1		*REAR TAILGATE LOWER PANEL	Repair	375.50 FL	*- FL
14	1		*REAR TAILLAMP BRACKET L/R	N/S Bent	123.60 FL	*61.80 FL
15	1		*REAR TAILLAMP L/R	N/S Cracked	502.60 FL	*251.30 FL
16	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
17	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
18	1		*SET REAR REVERSE SENSOR BRACKET	Necessary	90.00 FS	*50.00 FS
19	1		*REAR TAILGATE 13 PAX STICKER	Necessary	25.00 FS	*15.00 FS
20	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
21	1		*REAR UNDER BUMPER	Bent	1,200.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,097.40	3,587.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,120.60	645.65
Total Parts (\$\$)	4,976.80	2,941.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
3	TO REMOVE AND REINSTALL EXHAUST PIPE	New	120.00	80.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY ,STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	40.00
Gross Labour Cost (S\$)			2,260.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >