


## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SME 6702M Yr Regn: 11/10/18  
 Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mitsubishi Attage c.c. 1193  
 Colour: White A/C: Insured / Std / Nil / NA  
 Sp. Reading: 49398 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MMBS1A13A3H002566  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / 6Rim / STD A/Rim or  
 Tyre Size: F: 185/55R15  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm	
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm	
D.O.A. <u>11/10/22</u>		D.O.I. <u>7/10/22</u>	
Survey held at <u>Cycle</u>			
Des. of Damages: Frt / <u>Rear</u> / O/S / N/S / UIC / Rooftop or			

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-64K</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.H. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL




CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ang Jie	Cust No/Name /Ang Jie
624 Senja Road	Reg No/Reg Date SME6702M / 11/10/201
#06-98	Date In/Mileage / 0
Singapore 670624	Chassis No MMBSTA13AJH002566
Contact No Mobile: 96673272	Engine No 3A92UHC3753
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	03/10/2022/ 17:50		442 / CocoLu	27741

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR BOOTLID, REAR END PANEL, REAR FENDER RH	2 x 640			1280 2560.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH	7 x 550			1650 2200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80 100.00
M SUNDRY SUPPLY PARKING SENSOR				? 280.00
M SUNDRY C&C LOGO				50.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00
M SUNDRY Sundry				20.00
M FACE,RR BUMPER	1.00	1242.00	00.00	1242.00
M BRACKET,RR BUMPER,RH	1.00	34.00	00.00	34.00
M LATCH,TRUNK LID	1.00	220.00	00.00	220.00
M MARK,THREE-DIA	1.00	84.00	00.00	84.00
M MARK,ATTRAGE	1.00	25.00	00.00	25.00
M REFLECTOR	1.00	27.00	00.00	27.00

Estimate

Stew (LKK)

7/10/22, 12:00pm

WL M

PIP

M PRL

Confirm &amp; accepted by

5 days

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Reparer

Signature:

Date:

Nett 7,172.00  
7% GST on 7172.00 502.04  
Total Payable 7,674.04

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.