

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009767/RNY3Q2**Date:** 16/01/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00149892101

Claimant Vehicle No : SMF1177G**Insured Vehicle No :** GBJ799C

Date of Loss: 23/09/2022

Nature of Claim: TP

Claim No: SNM22D206879/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMF1177G**

Make & Model: BMW 220i, 2.0 COUPE MSPT ALED (A)

Engine No: 23666652B48B20A

Reg. Date: 11/05/2022 (Man. Year: 2022)

Chassis No: WBA12CM0X08C60742

Colour: Grey

Odometer: 5006 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R18

Rear Tyre Size: 255/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	275.65	114.50	161.15	58.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,573.00	2,087.00	486.00	18.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,848.65	2,201.50	647.15	22.72
+ GST 7.00/7.00% (S\$)	199.41	154.11	45.30	22.72
Nett Amount (S\$)	3,048.06	2,355.61	692.45	22.72

INSPECTION

Date of Assignment: 04/10/2022

Date Inspected: 21/11/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	M1-COUPE	BMW 220I 2.0 COUPE MSPT ALED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF1177G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*GRILLE AIR INLET MIDDLE	Not Necessary	121.15 FS	*- FS
3	1		*FRT NUMBER PLATE CARRIER (ECE)	Bent	74.50 FS	*74.50 FS
Total Parts (S\$)						275.65 114.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL BUMPER FRONT PANEL AND ATTACHMENT	New	1,275.00	850.00
2	TO SPRAY PAINT BUMPER FRONT PANEL	New	1,038.00	986.00
3	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	83.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
Gross Labour Cost (\$\$)			2,573.00	2,087.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >