

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22009774/EVY3Q2**Date:** 07/11/2022**REFERENCE**

Insured/Claimant: ONG CHU KIAT Policy No: DMPCSNW00161062200
Date of Loss: 02/10/2022 Nature of Claim: OD Claim No: SNM22D207021/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC8108Y**
Make & Model: LEXUS ES250, 2.5 4DR SEDAN EXECUTIVE (A) Engine No: A25A0237541
Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: JTHB11B1802003118
Colour: Green Odometer: 30134 km
Engine Capacity: 2487 cc
Market Value/New Car Price: S\$142,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,507.50	10,802.90	15,704.60	59.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,343.00	9,972.00	371.00	3.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,850.50	20,774.90	16,075.60	43.62
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	35,850.50	19,774.90	16,075.60	44.84
+ GST 7.00/7.00% (S\$)	2,509.54	1,384.24	1,125.30	44.84
Nett Amount (S\$)	38,360.04	21,159.14	17,200.90	44.84

INSPECTION

Date of Assignment: 04/10/2022
Date Inspected: 04/10/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462
Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2022)**Parts:** 143 LEXUS ES250 2.5 4DR SEDAN EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SGC8108Y)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*PANEL SUB-ASSY	Dented	902.00 FS	*902.00 FS
3	1		*HINGE ASSY ,LUGGAGE	Not Necessary	242.40 FS	*- FS
4	1		*HINGE ASSY ,LUGGAGE	Not Necessary	229.10 FS	*- FS
5	1		*COVER ,LUGGAGE	Not Necessary	543.90 FS	*- FS
6	14		*CLIP	Necessary	37.80 FS	*37.80 FS
7	1		*COVER ,LUGGAGE	Necessary	102.90 FS	*102.90 FS
8	1		*COVER ,LUGGAGE	Necessary	102.90 FS	*102.90 FS
9	1		*CLOSER ASSY ,LUGGAGE	Bent	1,394.60 FS	*1,394.60 FS
10	1		*WEATHERSTRIP	Crushed	272.70 FS	*272.70 FS
11	1		*GARNISH SUB-ASSY	Not Necessary	604.70 FS	*- FS
12	1		*LAMP SUB-ASSY	Not Necessary	311.50 FS	*- FS
13	1		*EMBLEM ,SYMBOL	Necessary	77.30 FS	*77.30 FS
14	1		*PLATE ,LUGGAGE COMPT	Necessary	73.80 FS	*73.80 FS
15	1		*PLATE ,LUGGAGE COMPT	Necessary	73.80 FS	*73.80 FS
16	1		*LAMP ASSY ,RR ,RH	Not Necessary	1,149.20 FS	*- FS
17	1		*LAMP ASSY ,RR ,LH	Not Necessary	1,149.20 FS	*- FS
18	2		*CLIP	Not Necessary	7.80 FS	*- FS
19	1		*SUPPORT ,RR BUMPER	Broken	147.30 FS	*147.30 FS
20	1		*SUPPORT ,RR BUMPER	Not Necessary	147.30 FS	*- FS
21	1		*INSERT ,RR BUMPER	Necessary	27.20 FS	*27.20 FS
22	1		*INSERT ,RR BUMPER	Necessary	27.20 FS	*27.20 FS
23	1		*PROTECTOR ,RR	Necessary	200.30 FS	*200.30 FS
24	1		*PROTECTOR ,RR	Necessary	201.90 FS	*201.90 FS
25	1		*REINFORCEMENT ,RR	Not Necessary	802.50 FS	*- FS
26	1		*ABSORBER ,RR BUMPER	Not Necessary	120.90 FS	*- FS
27	1		*SUPPORT ,RR BUMPER	Not Necessary	85.00 FS	*- FS
28	1		*SUPPORT ,RR BUMPER	Not Necessary	92.80 FS	*- FS
29	1		*RETAINER ,RR BUMPER	Not Necessary	149.70 FS	*- FS
30	1		*COVER ,RR BUMPER	Broken	1,403.40 FS	*1,403.40 FS
31	2		*TAPE ,MOULDING ,NO.1	Necessary	86.00 FS	*86.00 FS
32	1		*BUMPER SUB-ASSY ,RR	Broken	732.40 FS	*732.40 FS
33	1		*BRACKET ,KICK DOOR	Not Necessary	155.20 FS	*- FS
34	1		*SENSOR ,KICK DOOR	Not Necessary	749.30 FS	*- FS
35	17		*PIECE ,RR BUMPER	Necessary	76.50 FS	*76.50 FS
36	4		*RETAINER ,ULTRASONIC	Necessary	76.80 FS	*76.80 FS
37	4		*CLIP ,ULTRASONIC	Necessary	51.60 FS	*51.60 FS
38	4		*SENSOR ,ULTRASONIC	Not Necessary	1,965.60 FS	*- FS
39	1		*REFLECTOR ASSY	Not Necessary	52.80 FS	*- FS
40	1		*REFLECTOR ASSY	Not Necessary	52.80 FS	*- FS
41	1		*WIRE ,LUGGAGE ROOM	Not Necessary	192.10 FS	*- FS
42	2		*SENSOR ,BLIND SPOT	Not Necessary	4,327.40 FS	*- FS
43	1		*COVER ,BLIND SPOT	Not Necessary	97.40 FS	*- FS
44	1		*COVER ,BLIND SPOT	Not Necessary	97.40 FS	*- FS
45	1		*LAMP ASSY ,RR	Cut	1,476.70 FS	*1,476.70 FS
46	1		*LAMP ASSY ,RR	Cut	1,476.70 FS	*1,476.70 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*COVER ,RR	Necessary	40.60 FS	*40.60 FS
48	1		*COVER ,RR	Necessary	40.60 FS	*40.60 FS
49	2		*GUIDE ,RR	Necessary	7.80 FS	*7.80 FS
50	2		*GUIDE ,RR	Necessary	5.60 FS	*5.60 FS
51	1		*RETAINER ,RR BUMPER	Necessary	65.00 FS	*65.00 FS
52	1		*RETAINER ,RR BUMPER	Necessary	65.00 FS	*65.00 FS
53	1		*CARRIER ,SPARE WHEEL	Not Necessary	28.10 FS	*- FS
54	1		*TRAY ,SPARE WHEEL	Not Necessary	280.50 FS	*- FS
55	1		*MAT ,LUGGAGE	Not Necessary	777.60 FS	*- FS
56	1		*BOX ,LUGGAGE	Not Necessary	763.60 FS	*- FS
57	1		*PLATE ,RR FLOOR	Crushed	389.60 FS	*389.60 FS
58	1		*PANEL SUB-ASSY,BODY	Dented	908.50 FS	*908.50 FS
59	1		*ANTENNA ,ELECTRICAL	Not Necessary	78.00 FS	*- FS
60	1		*PROTECTOR ,QUARTER	Necessary	30.90 FS	*30.90 FS
61	1		*PROTECTOR ,QUARTER	Necessary	30.90 FS	*30.90 FS
62	1		*PROTECTOR ,RR DOOR	Necessary	25.30 FS	*25.30 FS
63	1		*PROTECTOR ,RR DOOR	Necessary	25.30 FS	*25.30 FS
64	1		*COVER ,RR FLOOR SIDE	Not Necessary	420.80 FS	*- FS
65	1		*SUPPLY REGN PLATE (PO#) REAR	Cut	96.00 FS	*96.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	26,507.50	10,802.90
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW DOOR SHELL	New	433.00	433.00
2	REMOVE/REFIX REVERSE CAMERA	New	216.50	216.50
3	REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR	New	433.00	433.00
4	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE	New	216.50	216.50
5	REMOVE/REFIX REVERSE SENSOR	New	216.50	216.50
6	REMOVE ALL NECESSARY PARTS TO ENABLE REAIRING AND STRAIGHTEN REAR PANEL ,SPARE WHEEL PAN ,R/R AND L/R BODY PANELS ,CUT AND WELD PANEL AND FIT NEW PARTS	New	4,330.00	4,330.00
7	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	4,081.00	3,710.00
8	SUPPLY SEALANT .BOOT AND REAR PANEL	New	200.00	200.00
9	TO RESET ECU AND REPROGRAMME	New	216.50	216.50
Gross Labour Cost (\$)			10,343.00	9,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >