

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009776/KQY3Q2**Date:** 10/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00010532200
<b>Claimant Vehicle No :</b>	SJP7987D	<b>Insured Vehicle No :</b>	SLQ6373C
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207056/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJP7987D</b>	Engine No:	R18A1804573
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61094357
Reg. Date:	09/04/2009 (Man. Year: 2008)	Odometer:	218567 km
Colour:	Metallic Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,230.96	1,979.94	1,251.02	38.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	1,280.00	1,610.00	55.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,120.96</b>	<b>3,259.94</b>	<b>2,861.02</b>	<b>46.74</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,600.00</b>		
<b>(\$\$)</b>	6,120.96	2,600.00	3,520.96	57.52
<b>+ GST 7.00/7.00% (\$\$)</b>	428.47	182.00	246.47	57.52
<b>Nett Amount (\$\$)</b>	<b>6,549.43</b>	<b>2,782.00</b>	<b>3,767.43</b>	<b>57.52</b>

**INSPECTION**

Date of Assignment:	04/10/2022	
Date Inspected:	05/10/2022 Inspected At:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2022)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJP7987D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	903.20 FL	*903.20 FL
2	1		*SET REAR TAILGATE WINDSCREEN MOULDING	Necessary	85.60 FL	*85.60 FL
3	1		*REAR TAILGATE LOGO	Not Necessary	31.90 FL	*- FL
4	1		*REAR TAILGATE H EMBLEM PANEL	Not Necessary	262.40 FL	*- FL
5	1		*REAR TAILGATE LOGO STREAM	Necessary	41.60 FL	*41.60 FL
6	1		*REAR TAILGATE RUBBER (50%)	Cut	135.52 FS	*84.70 FS
7	1		*REAR BUMPER	Bent	678.20 FL	*678.20 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	29.40 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	29.40 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Dented	216.70 FL	*216.70 FL
11	1		*REAR END PANEL INNER	Repair	98.20 FL	*- FL
12	1		*REAR END PANEL OUTER	Repair	394.20 FL	*- FL
13	1		*TOWING COVER	Serviceable	23.50 FL	*- FL
14	1		*EXHAUST TIP	Serviceable	300.00 FL	*- FL
15	1		*SET REAR NUMBER PLATE WITH FRAME	Dented	50.00 FS	*45.00 FS
16	1		*SET REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS
17	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
18	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	35.00 FS	*35.00 FS
19	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
20	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,849.82</b>	<b>2,365.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	618.86	385.06
<b>Total Parts (\$\$)</b>	<b>3,230.96</b>	<b>1,979.94</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	600.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGED PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	400.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	30.00
5	TO REMOVE /REFIX /REPLACE REAR REVERSE CAMERA	New	150.00	0.00
6	TO REMOVE/REFIX /REPLACE REAR TAILGATE INNER COMPARTMENT,MECHANISM TO NEW TAILGATE	New	200.00	60.00
7	TO REMOVE /REPLACE REAR TAILGATE GLASS	New	150.00	120.00
8	TO REMOVE/REFIX REVERSE SENSOR	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,890.00</b>	<b>1,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >