

ASS. REC. BY:

Steve

CC4/AIS/2009.779/EPA3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

EstL Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKD 6362P Yr Regn: 20/8/09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato c.c. 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 733648 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFWU12MA5106755

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SRM / STD A/Rlm or

Tyre Size: F: 185/55R15R: 11BS / DUN / EXNOVA / ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm U/Bal. 4 mmD.O.A. 1/10/22 D.O.I. 4/10/22Survey held at ARCDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NIR-68X

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : 2210-537-TG

DATE : 3-Oct-2022

POLICY NO. :

VEHICLE REG. NO. : SKD6362P

VEHICLE MAKE : KIA CERATO 2.0L SX A/T SR ABS D/AB 2

TO Motor Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / <i>DD</i>	1	\$ 598.00	\$ 598.00
2	Rear Bumper Side Retainer LH/RH / <i>SR</i>	(2)	\$ 41.00	\$ 82.00
3	Rear Bumper Reinforcement / <i>SR</i>	1	\$ 352.00	\$ 352.00
4	Rear Bumper Lower Garnish / <i>CR4</i>	1	\$ 151.00	\$ 151.00
5	Rear Boot / <i>DD</i>	1	\$ 1,000.00	\$ 1,000.00
6	Rear Boot Lock / <i>BT</i>	1	\$ 155.00	\$ 155.00
7	Rear Boot Hinge LH/RH / <i>X R</i>	2	\$ 82.00	\$ 164.00
8	Rear Boot Weatherstrip / <i>CR4</i>	1	\$ 110.00	\$ 110.00
9	Rear Boot Emblem / <i>MC</i>	1	\$ 63.00	\$ 63.00
10	Rear Boot Logo (2.0) / <i>MC</i>	1	\$ 58.00	\$ 58.00
11	Rear End Panel / <i>DD</i>	1	\$ 312.00	\$ 312.00
12	Rear End Panel Top Garnish / <i>CR4</i>	1	\$ 72.00	\$ 72.00
Parts Less 20%				\$ (623.40)
Total Spare Parts				\$ 2,493.60
SPECIAL NETT				
13	Sealant On Rear End Panel / <i>MC</i>	1	\$ 40.00	\$ 40.00
14	Rear Bumper Clips / <i>MC</i>	10	\$ 5.00	\$ 50.00
15	Rear Reverse Sensor / <i>Shiru</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 290.00
LABOUR				
16	Remove, Replace and Repair Accident Affected Area	1	\$ 800.00	\$ 800.00
17	Spray Painting (Rear Bumper, Rear Boot, Rear End Panel)	1	\$ 800.00	\$ 800.00
18	Remove and replace Reverse Sensor	1	\$ 60.00	\$ 60.00
19	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 1,710.00
Amount Before Excess				\$ 4,493.60
Add GST @ 7%				314.55
Total Amount Payable				\$ 4,808.15

Estimate prepared by: James Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. To reserve price for spray paint, the quotation on parts and labour are current and subject to change.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: