

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22009784/GQY3M4**Date:** 18/04/2023**REFERENCE**

Insured/Claimant: YI XIANG RENOVATION PRIVATE LIMITED  
Date of Loss: 28/07/2022

Policy No: DMCG22002212

Nature of Claim: OD

Claim No: CDMCG22001511

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBK9945H**  
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)  
Reg. Date: 09/02/2021 (Man. Year: 2020)  
Colour: Silver  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$94,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: 1KDB069146  
Chassis No: JTFAT35Y70K216290  
Odometer: 35838 km

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/75R15 Rear Tyre Size: 155R12  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,283.50	2,108.70	1,174.80	35.78
Miscellaneous Items	55.00	15.00	40.00	72.73
Labour	1,410.00	950.00	460.00	32.62
Paintwork Labour	780.00	600.00	180.00	23.08
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,528.50</b>	<b>3,673.70</b>	<b>1,854.80</b>	<b>33.55</b>
<b>- Excess (\$\$)</b>	500.00	500.00	0.00	0.00
<b>(\$\$)</b>	5,028.50	3,173.70	1,854.80	36.89
<b>+ GST 7.00/8.00% (\$\$)</b>	352.00	253.90	98.10	27.87
<b>Nett Amount (\$\$)</b>	<b>5,380.50</b>	<b>3,427.60</b>	<b>1,952.90</b>	<b>36.30</b>

**INSPECTION**

Date of Assignment: 04/10/2022 Present Location: Kan Fook Sing Motor Workshop (Defu)  
KAN FOOK SING MOTOR WORKSHOP  
Date Inspected: 05/10/2022 Inspected At: BLK.8 JTC DEFU INDUSTRIAL CITY  
#04-29 DEFU SOUTH STREET 1  
SINGAPORE 533758  
Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Apr 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9945H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (WCP)	Cracked	350.00 F	*450.00 F
2	1		*FRONT WINDSCREEN RUBBER (WCP)	Necessary	95.00 F	*95.00 F
3	1		*FRONT WIPER PANEL (WCP)	Deformed	130.00 F	*130.00 F
4	1		*FRONT PANEL (WCP)	Buckled	390.00 F	*400.00 F
5	1		*FRONT PANEL DYNE EMBLEM (WCP)	Necessary	28.00 F	*28.00 F
6	1		*FRONT GRILLE (WCP)	Cut	175.00 F	*175.00 F
7	1		*FRONT GRILLE EMBLEM (WCP)	Not Necessary	28.00 F	*- F
8	1		*FRONT HEADLAMP LH (WCP)	Cut	300.00 F	*300.00 F
9	1		*FRONT BUMPER (WCP)	Bent	220.00 F	*220.00 F
10	1		*FRONT BUMPER BRACKET RH (WCP)	Not Necessary	95.00 F	*- F
11	1		*FRONT BUMPER BRACKET LH (WCP)	Bent	95.00 F	*95.00 F
12	1		*AIR CON BLOWER (WCP)	Not Necessary	900.00 F	*- F
13	1		*HEATER UNIT (WCP)	Not Necessary	155.00 F	*- F
14	8		*FRONT GRILLE CLIP (WCP)	Necessary	24.00 F	*24.00 F
F=Franchise part.						
Sub Total (\$\$)					2,985.00	1,917.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					298.50	191.70
Total Parts (\$\$)					3,283.50	2,108.70

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	ERP STICKER (Necessary)	15.00	15.00
2	1	FRONT NUMBER PLATE (Not Necessary)	40.00	0.00
<b>Sub Total (\$\$)</b>			<b>55.00</b>	<b>15.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	SPRAYPAINTING CHARGES	New	780.00	600.00
<b>Labour Items</b>				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	120.00	120.00
4	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	220.00	0.00
5	TO REMOVE ALL NECESSARY AFEFCTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	820.00	600.00
<b>Supplementary #1</b>				
<b>Labour Items</b>				
6	TO REMOVE & REFIT DASHBOARD ASSY TO FACILITATE FRONT PANEL REPLACEMENT	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,190.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >