



簡 福 星 嘜 工 廠

KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6261 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221468-00E

GST Reg. No. M9-0005333-E

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22002212	Date of Loss:	28/07/2022
Vehicle Reg. No.:	GBK9945H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YI XIANG RENOVATION PTE LTD		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	09/02/2021
Vehicle Colour:	METALLIC SILVER		
Engine No:	1KD8069146	Chassis No:	JTFAT35Y70K216290
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	3,283.50
Miscellaneous Items	55.00
Labour	1,210.00
Paintwork Labour	780.00
Towing	0.00
Calculated Gross Total (S\$)	5,328.50
- Excess (S\$)	500.00
(S\$)	4,828.50
+ GST 7.00% (S\$)	338.00
Nett Amount (S\$)	5,166.50

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Aug 2022)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS <i>✓ CHA</i>	0.00	0.00	*350.00 F
2	1		*FRONT WINDSCREEN RUBBER <i>✓ mcl</i>	0.00	0.00	*95.00 F
3	1		*FRONT WIPER PANEL <i>✓ ee</i>	0.00	0.00	*130.00 F
4	1		*FRONT PANEL <i>✓ fmc</i>	0.00	0.00	*390.00 F
5	1		*FRONT PANEL DYNE EMBLEM <i>✓ mcl</i>	0.00	0.00	*28.00 F
6	1		*FRONT GRILLE <i>✓ CA</i>	0.00	0.00	*175.00 F
7	1		*FRONT GRILLE EMBLEM <i>✓ mcl</i>	0.00	0.00	*28.00 F
8	1		*FRONT HEADLAMP LH <i>✓ CA</i>	0.00	0.00	*300.00 F
9	1		*FRONT BUMPER <i>✓ BT</i>	0.00	0.00	*220.00 F
10	1		*FRONT BUMPER BRACKET RH <i>?</i>	0.00	0.00	*95.00 F
11	1		*FRONT BUMPER BRACKET LH <i>?</i>	0.00	0.00	*95.00 F
12	1		*AIR CON BLOWER <i>?</i>	0.00	0.00	*900.00 F
13	1		*HEATER UNIT <i>?</i>	0.00	0.00	*155.00 F
14	8		*FRONT GRILLE CLIP <i>✓ mcl</i>	0.00	0.00	*24.00 F

F=Franchise part.

Sub Total (S\$)	2,985.00
+ Margin on L,N Items 10.00% (S\$)	298.50
Total Parts (S\$)	3,283.50

Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	ERP STICKER <i>MC</i>	15.00
2	1	FRONT NUMBER PLATE <i>X NN</i>	40.00
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	<i>600</i> 780.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New	<i>30</i> 50.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	<i>1</i> 120.00
4	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New	<i>3</i> 220.00
5	TO REMOVE ALL NECESSARY AFEFCTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	<i>600</i> 820.00
Gross Labour Cost (S\$)			1,990.00

Kan Fook Sing Motor Workshop/GBK9945H/16/08/2022 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess: 500

Not Authorized.

Gmo Q: 4

5/10/22

5 Days.

P/P

before painting works.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are based on market
- Third party supply on "no prejudice" basis
- No illegal practices allowed
- Supplemental claims are allowed and is subject to insurance company

Acknowledged by Repairer:
Signature:
Date: