

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7270J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FOOTGEAR LEVER	BENT	130.00	90.00
1	L/S PILLION FOOT REST	SCRATCHED	95.00	52.00
	LESS 10% DISCOUNT		-22.50	-14.20
			202.50	127.80
	SPECIAL NETT ITEMS			
1	SET CRASH BAR (SN)	BENT	160.00	160.00
1	SET CARGO ROUND CONTAINER (SN)	SCRATCHED	95.00	20.00
1	YOSHIMURA EXHAUST END CAN W/CERTIFICATE (SN)	BENT	1,850.00	1,400.00
			2,105.00	1,580.00
	<u>LABOUR</u>			
	LABOUR CHARGE FOR PART REPLACEMENT.		160.00	140.00
			160.00	140.00
	GRAND TOTAL		2,467.50	1,847.80

RECOMMENDED COST OF LUMP SUM REPAIRS		1,450.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22009790/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator