

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG22009794/AVY3E2**Date:** 09/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220092860
Claimant Vehicle No :	SLS6728C	Insured Vehicle No :	SMD8348U
Date of Loss:	30/09/2022	Nature of Claim:	TP
		Claim No:	0642021337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6728C		
Make & Model:	MERCEDES-BENZ E200 COUPE, 2.0 (R17) (A)	Engine No:	27492030067969
Reg. Date:	02/08/2013 (Man. Year: 2013)	Chassis No:	WDDKJ3EB2EF225564
Colour:	Grey	Odometer:	108371 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,776.20	10,192.10	8,584.10	45.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	2,230.00	1,740.00	43.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,746.20	12,422.10	10,324.10	45.39
Approved Total (Overridden) (S\$)		9,900.00		
Nett Amount (S\$)	22,746.20	9,900.00	12,846.20	56.48

INSPECTION

Date of Assignment:	04/10/2022		
Date Inspected:	04/10/2022	Inspected At:	Tsl Auto Garage (HQ) Blk 1 Kaki Bukit Avenue 6 #01-08 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID ASSY	Dented	1,753.00 FL	*1,753.00 FL
2	1		*REAR BOOTLID LOGO	Necessary	88.00 FL	*88.00 FL
3	1		*REAR BOOTLID WEATHERSTRIP	Cut	216.00 FL	*216.00 FL
4	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	226.00 FL	*- FL
5	1		*REAR BOOTLID LOCK INNER COVER	Damaged	165.00 FL	*165.00 FL
6	1		*REAR BOOTLID LOCK MECHANISM	Damaged	267.00 FL	*267.00 FL
7	2		*REAR BOOTLID RUBBER STOPPER	Not Necessary	68.00 FL	*- FL
8	1		*REAR BOOTLID BREAKDOWN WARNING SIGN	Not Necessary	180.00 FL	*- FL
9	2		*REAR BOOTLID HINGES	Not Necessary	195.00 FL	*- FL
10	2		*REAR BOOTLID HINGES COVER	Not Necessary	187.00 FL	*- FL
11	1		*REAR BOOTLID E200 EMBLEM	Necessary	81.00 FL	*81.00 FL
12	1		*REAR BOOTLID CYCLE CARRIAGE EMBLEM	Necessary	86.00 FL	*86.00 FL
13	1		*REAR BOOTLID 7G EMBLEM	Necessary	76.00 FL	*76.00 FL
14	1		*REAR BOOTLID TRONIC EMBLEM	Necessary	82.00 FL	*82.00 FL
15	1		*REAR BOOTLID CHROME MOULDING	Cracked	199.00 FL	*199.00 FL
16	1		*REAR LEFT TAILLAMP	Cracked	828.00 FL	*828.00 FL
17	1		*REAR RIGHT TAILLAMP	Not Necessary	828.00 FL	*- FL
18	1		*REAR BOOTLID LEFT TAILLAMP	Cracked	623.00 FL	*425.00 FL
19	1		*REAR BOOTLID RIGHT TAILLAMP	Not Necessary	623.00 FL	*- FL
20	1		*REAR END PANEL	Dented	1,265.00 FL	*1,180.00 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	182.00 FL	*182.00 FL
22	1		*REAR BUMPER ASSY	Deformed	1,690.00 FL	*1,690.00 FL
23	1		*REAR BUMPER CENTER CHROME MOULDING	Cut	380.00 FL	*380.00 FL
24	1		*REAR BUMPER LEFT CHROME MOULDIG	Necessary	196.00 FL	*196.00 FL
25	1		*REAR BUMPER RIGHT CHROME MOULDING	Necessary	196.00 FL	*196.00 FL
26	1		*REAR BUMPER LOWER TRIM	Deformed	455.00 FL	*455.00 FL
27	1		*REAR BUMPER TOW COVER	Not Necessary	98.00 FL	*- FL
28	1		*REAR BUMPER INNER LOCK SWITCH SENSOR	Not Necessary	375.00 FL	*- FL
29	1		*REAR BUMPER INNER BRAKE ASSIST SENSOR	Not Necessary	380.00 FL	*- FL
30	1		*REAR BUMPER REINFORCEMENT	Dented	990.00 FL	*780.00 FL
31	1		*REAR BUMPER LEFT SIDE RETAINER	Not Necessary	81.00 FL	*- FL
32	1		*REAR BUMPER RIGHT SIDE RETAINER	Not Necessary	81.00 FL	*- FL
33	1		*REAR BUMPER LEFT TOP BASIC CARRIER	Cracked	67.00 FL	*67.00 FL
34	1		*REAR BUMPER RIGHT TOP BASIC CARRIER	Cracked	67.00 FL	*67.00 FL
35	1		*REAR BUMPER LEFT BOTTOM BASIC CARRIER	Not Necessary	88.00 FL	*- FL
36	1		*REAR BUMPER RIGHT BOTTOM BASIC CARRIER	Not Necessary	88.00 FL	*- FL
37	1		*REAR BUMPER LEFT SIDE STABILITY	Not Necessary	165.00 FL	*- FL
38	1		*REAR BUMPER RIGHT SIDE STABILITY	Not Necessary	165.00 FL	*- FL
39	1		*REAR BUMPER CENTER BRACKET	Cracked	155.00 FL	*155.00 FL
40	1		*REAR BUMPER LEFT LOWER BRACKET	Not Necessary	62.00 FL	*- FL
41	1		*REAR BUMPER RIGHT LOWER BRACKET	Not Necessary	62.00 FL	*- FL
42	1		*REAR MERCEDES BENZ PARKING SENSOR (4PCS)	Damaged (2Pcs Only)	1,528.00 FL	*560.00 FL
43	1		*REAR EXHAUST SILENCER ASSY	Not Necessary	1,487.00 FL	*- FL
44	2		*REAR EXHAUST MOUNTINGS	Not Necessary	88.00 FL	*- FL
45	1		*REAR SPARE TYRE TOP BOARD	Deformed	295.00 FL	*295.00 FL
46	2		*REAR NO PLATE LAMP	Not Necessary	128.00 FL	*- FL
47	1		*REAR TOOL SPONGE CARRIER	Not Necessary	295.00 FL	*- FL
48	1		*REAR BOOTLID KEY LOCK	Not Necessary	126.00 FL	*- FL
49	1		*REAR LEFT EXHAUST HEAT SHIELD	Not Necessary	167.00 FL	*- FL
50	1		*REAR RIGHT EXHAUST HEAT SHIELD	Not Necessary	167.00 FL	*- FL
51	1		*REAR CENTRE EXHAUST HEAT SHIELD	Not Necessary	178.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
54	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
55	1		*REAR VIEW CAMERA	Damaged	450.00 FS	*380.00 FS
56	1		*REAR BOOTLID THIRD BRAKE LAMP	Cut	450.00 FS	*280.00 FS
57	1		*REAR BOOTLID TOP SPOILER SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*REAR BOOTLID TOP SPOILER	Not Necessary	750.00 FS	*- FS
59	1		*REAR LICENSE PLATE	Not Necessary	100.00 FS	*- FS
60	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,628.00	11,239.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,851.80	1,046.90
Total Parts (\$)	18,776.20	10,192.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,600.00	900.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,600.00	900.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR BOOTLID FITTINGS	New	80.00	80.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	60.00
7	TO REMOVE AND INSTALL REAR EXHAUST SILENCER ASSY	New	120.00	0.00
8	TO REMOVE AND INSTALL REAR PARKING SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	50.00
10	TOWING SERVICE	New	100.00	100.00
Gross Labour Cost (\$\$)			3,970.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >