



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301508

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/03/2023
Reference CC6/CTI22009800/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJH 8966A
Insured Veh. GBD 455B
Claim No. SNM22D207111/C02
Policy No. DMCVSNW00143372100
Accident Date 29/09/2022
Inspection Date 04/10/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22009800/Kpa3q2 Date: 14/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 455B	Veh. Inspected	SJH 8966A	
Policy No.	DMCVSNW00143372100	Coverage (\$)	0.00	
Claim No.	SNM22D207111/C02	Excess (\$)	0.00	
Assign From		Assign Date	04/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	TESLA MODEL 3 (A)	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	LRW3F7FJXMC263263	Colour	METALLIC PEARL WHITE	
Odometer	21189 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45Z R18	MICHELIN	8 mm	
L/H Front Tyre	235/45Z R18	MICHELIN	8 mm	
R/H Rear Tyre	235/45Z R18	MICHELIN	8 mm	
L/H Rear Tyre	235/45Z R18	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2022	Inspection Date	04/10/2022	
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 8966A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR RH	TO REPAIR SEE LABOUR	953.27	-
1	REAR DOOR WEATHERSTRIP RH	SERVICEABLE	88.79	-
1	REAR FENDER RH	BENT	1,345.79	1,345.79
1	REAR FENDER QUARTER GLASS RH	MTG NECESSARY	280.37	280.37
	LESS 10% DISCOUNT		-266.82	-162.62
			2,401.40	1,463.54
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER QUARTER GLASS SEALANT RH (SN)	NECESSARY	80.00	40.00
			130.00	40.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR DOOR RH .		600.00	600.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH ,REAR FENDER RH & ETC.		600.00	440.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC.TO EFFECT REPLACE OF REAR DOOR RH .	NOT NECESSARY	150.00	-
	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLSTERY CUSHION SET & ETC.TO EFFECT REPLACE OF REAR FENDER RH .		300.00	100.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS RH,REAR FENDER QUARTER GLASS SEALANT RH & ETC.		150.00	60.00
	TO CHECK WIRING & ELECTRICAL SYSTEM.		120.00	20.00
			1,920.00	1,220.00
	GRAND TOTAL		4,451.40	2,723.54



RECOMMENDED COST OF REPAIRS			2,723.54
-----------------------------	--	--	----------

Report Ref No. CC6/CT122009800/Kpa3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 8966A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

