

ASS. REC. BY:

REF:

C72 / 22009808/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNA 3532R

Yr Regn:

06, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

19176

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU 1

1321080

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

17/9/22

D.O.I.

3/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ EH not ready

8/10 @ 1535.92 Carhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. \$

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SLR 4332 D
Accident Date : 17-Sep-2022

Our Ref : 022284 (CHINA) / MH

LEE LIAN SENG (MR)
Singapore

No. : 32548

Date : 19-Sep-2022

PAGE : 1

*Not Authorized
Permy B4 Point
3 days*

81535.92

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2021) SNA3532R

1 pc rear bumper	<i>Brd/Wr</i> 463.70	✓
1 pc n/s rear bumper side retainer	<i>oil</i> 18.00	—
1 pc rear bumper - side	<i>Brd/Wr</i> 172.80	—
10 pcs rear bumper clip	@ S\$ 3.50 <i>m</i> 35.00	—
1 pc n/s rear bumper reflector	<i>Sh</i> 141.00	X
1 pc tailgate 'Vezel' emblem	<i>m</i> 45.80	—
1 pc n/s rear fender wheel arch garnish	<i>Rd</i> 172.10	—
	1,048.40	
	Less 20% : -209.68	
	838.72	
1 pc reverse sensor assy	<i>m</i> 220.00	sn X
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	480.00	<i>360</i>
To remove and refit reverse sensor assy.	60.00	<i>50</i>
To putty and respray on affected portions.	450.00	<i>400</i>
	Total : S\$ 2,048.72	

Singapore Dollars TWO THOUSAND FORTY EIGHT AND CENTS SEVENTY TWO Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: