



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4597T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 503.04 | - |
| 10 | REAR BUMPER CLIPS | NECESSARY | 22.00 | 22.00 |
| 1 | TOWING COVER | MISSING | 82.70 | 82.70 |
| 1 | REAR BUMPER REINFORCEMENT | NOT NECESSARY | 378.32 | - |
| 1 | REAR BUMPER LOWER COVER | DEFORMED | 654.96 | 654.96 |
| | LESS 25% DISCOUNT | | -410.26 | -189.92 |
| | | | 1,230.76 | 569.74 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER. | | 400.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 300.00 | 250.00 |
| | REMOVE / REFIX REVERSE SENSOR. | | 60.00 | 30.00 |
| | | | 760.00 | 630.00 |
| GRAND TOTAL | | | 1,990.76 | 1,199.74 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | | 950.00 |

Report Ref No. NS/INC22009813/Tqce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.