

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4777R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	TORN	586.18	586.18
1	HEADLAMP ASSY LH	CRACKED	2,637.60	2,637.60
2	FOG LAMP RH/LH	CUT	920.00	920.00
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
2	FRT BUMPER TOW COVER RH/LH @\$28.38	MISSING	56.76	56.76
1	FRT RADIATOR GRILLE	NOT NECESSARY	438.00	-
1	FRT BUMPER GRILLE	CUT	193.18	193.18
1	FRT BUMPER SPONGE	CRACKED	78.80	78.80
1	EMBLEM 'H'	NECESSARY	88.00	88.00
1	HEADLAMP CENTRE PANEL	NOT NECESSARY	364.98	-
1	FRT BUMPER BEAM	NOT NECESSARY	812.89	-
1	FRT RH BUMPER SIDE BRACKET LH	NOT NECESSARY	82.30	-
2	HEADLAMP PANEL LH @\$240.10	NOT NECESSARY	480.20	-
1	FRT NUMBER PLATE GARNISH	MISSING	99.00	99.00
	LESS 25% DISCOUNT		-1,714.97	-1,170.38
			5,144.92	3,511.14
	NETT ITEMS			
1	FRT NUMBER PLATE (N)	MISSING	50.00	50.00
	LESS 10% DISCOUNT		-	-5.00
			50.00	45.00
	<u>LABOUR</u>			
	PANEL BEAT.		800.00	350.00
	SPRAYPAINT.		300.00	250.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	TOWING FEE.		60.00	-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX A/C AND REFILL GAS.	NOT NECESSARY	120.00	-
			1,380.00	630.00
	GRAND TOTAL		6,574.92	4,186.14

RECOMMENDED COST OF LUMP SUM REPAIRS		3,350.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22009815/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser