



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2547R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER COVER	DEFORMED	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET RH	DEFORMED	28.00	28.00
1	FRT BUMPER MOULDING CENTRE UPPER	CRACKED	368.50	368.50
1	HEADLAMP RH	NOT NECESSARY	2,110.30	-
1	DAY LIGHT RH	CUT	642.50	642.50
1	FRT BUMPER SIDE MOULDING RH	CUT	93.60	93.60
1	EMBLEM -BLUE DRIVE RH	NOT NECESSARY	26.60	-
	LESS 20% DISCOUNT		-754.52	-327.14
			3,018.08	1,308.56
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT STICKER RH (SN)	NOT NECESSARY	100.00	-
			100.00	-
<u>LABOUR</u>				
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK ALL LIGHTING.		60.00	30.00
			1,520.00	630.00
GRAND TOTAL			4,638.08	1,938.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,550.00

Report Ref No. NS/INC22009816/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.