

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22009825/RCY3Q2**Date:** 23/05/2023**REFERENCE**

Insured/Claimant: ONG KENG BOON Policy No: MPC22B00032000
Date of Loss: 24/09/2022 Nature of Claim: OD Claim No: DMPC2200439H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB3994K**
Make & Model: TOYOTA NOAH, 1.8 (A) Engine No: 2ZR2M86676
Reg. Date: 19/08/2021 (Man. Year: 2021) Chassis No: ZWR800507003
Colour: Black Odometer: 28397 km
Engine Capacity: 1797 cc
Market Value/New Car Price: S\$172,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17 Rear Tyre Size: 215/50Z R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,695.50	7,766.00	929.50	10.69
Miscellaneous Items	661.00	112.50	548.50	82.98
Labour	1,710.00	1,120.00	590.00	34.50
Paintwork Labour	1,250.00	1,000.00	250.00	20.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,316.50	9,998.50	2,318.00	18.82
Approved Total (Overridden) (S\$)		8,000.00		
- Excess (S\$)	0.00	500.00	-500.00	
Nett Amount (S\$)	12,316.50	7,500.00	4,816.50	39.11

INSPECTION

Date of Assignment: 05/10/2022 Present Location: Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ)
60 JALAN LAM HUAT
#04-53 CARROS CENTRE
SINGAPORE 737869
Date Inspected: 05/10/2022 Inspected At: Repairer: Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ)
Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3994K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air-cond condenser (WCP)	Bent	495.00 F	*495.00 F
2	1		Bumper bracket LH, front (WCP)	Cracked	30.00 F	*30.00 F
3	1		Bumper bracket RH, front (WCP)	Cracked	30.00 F	*30.00 F
4	1		Bumper protector center, front (WCP)	Cracked	95.00 F	*95.00 F
5	1		Bumper reinforcement, front (WCP)	Not Necessary	185.00 F	*- F
6	1		Bumper, front (WCP)	Cracked	290.00 F	*290.00 F
7	1		Headlamp LH (WCP)	Cracked	950.00 F	*950.00 F
8	1		Headlamp RH (WCP)	Cracked	950.00 F	*950.00 F
9	1		Panel, front (WCP)	Bent	600.00 F	*600.00 F
10	1		Radiator (WCP)	Bent	550.00 F	*550.00 F
11	1		W/screen glass moulding, front (WCP)	Necessary	60.00 F	*60.00 F
12	1		W/screen glass, front (WCP)	Cracked	780.00 F	*780.00 F
13	1		*Fender LH, front (WCP)	Bent	330.00 F	*330.00 F
14	1		*Fender RH, front (WCP)	Bent	330.00 F	*330.00 F
15	1		*GRILLE LOGO EMBLEM FRONT (WCP)	Scratched	55.00 F	*55.00 F
16	1		*GRILLE-RADIATOR (WCP)	Cracked	390.00 F	*390.00 F
17	1		*Bonnet (WCP)	Bent	380.00 F	*380.00 F
18	1		*Bonnet lock lower (WCP)	Bent	90.00 F	*90.00 F
19	1		*BRACE PANEL FRONT (WCP)	Bent	95.00 F	*95.00 F
20	1		*GRILLE UPPER (WCP)	Cracked	360.00 F	*360.00 F
21	1		*Fender bracket LH, front (WCP)	Necessary	20.00 F	*20.00 F
22	1		*Fender bracket RH, front (WCP)	Necessary	20.00 F	*20.00 F
23	1		*Horn (WCP)	Scratched	120.00 F	*120.00 F
24	1		*FENDER INNER TRIM LH (WCP)	Not Necessary	90.00 F	*- F
25	1		*FENDER INNER TRIM RH (WCP)	Not Necessary	90.00 F	*- F
26	1		*FENDER INNER TRIM RH CLIPS (WCP)	Necessary	20.00 F	*20.00 F
27	1		*FENDER INNER TRIM LH CLIPS (WCP)	Necessary	20.00 F	*20.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FOG LAMP LH (WCP)	Not Necessary	60.00 F	*- F
29	1		*FOG LAMP RH (WCP)	Not Necessary	60.00 F	*- F
30	1		*Headlamp bracket RH (WCP)	Not Necessary	80.00 F	*- F
31	1		*Headlamp bracket LH (WCP)	Not Necessary	80.00 F	*- F
32	1		*SENSOR, FRONT (WCP)	Not Necessary	200.00 F	*- F

F=Franchise part.

Sub Total (S\$)	7,905.00	7,060.00
+ Margin on L,N Items 10.00/10.00% (S\$)	790.50	706.00
Total Parts (S\$)	8,695.50	7,766.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Air-cond gas (R134A) (NECESSARY)	60.00	40.00
2	1	AIRCON COOLANT (NECESSARY)	30.00	30.00
3	1	GST (NOT NECESSARY)	528.50	0.00
4	1	Windscreen sealant, front (NECESSARY)	42.50	42.50
Sub Total (\$\$)			661.00	112.50

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	PUTTY/ SPRAY PAINT & POLISHING	New	1,250.00	1,000.00
Labour Items				
2	PANEL BEATING/ DISMANTLE& REFIX	New	1,200.00	800.00
3	DISMANTLE/ REFIX WINDSCREEN	New	100.00	100.00
4	DISMANTLE/REFIX AIRCON CONDENSER & RADIATOR	New	160.00	120.00
5	RESET FAULT CODE	New	200.00	100.00
6	REMOVE/REFIX FRONT SENSOR	New	50.00	0.00
Gross Labour Cost (\$\$)			2,960.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >