



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3722A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	BUCKLED	991.00	991.00
1	HEADLAMP LH	SERVICEABLE	2,161.00	-
1	HEADLAMP RH	SERVICEABLE	2,161.00	-
1	FRONT RADIATOR GRILLE 'B' SPECS	DENTED	632.20	632.20
1	FRONT RADIATOR GRILLE LOGO EMBLEM	CRACKED	102.60	102.60
4	FRONT RADIATOR GRILLE CLIPS (BIG) @\$4.00	NECESSARY	16.00	16.00
4	FRONT RADIATOR GRILLE CLIPS @\$4.00	NECESSARY	16.00	16.00
1	FRONT BUMPER	BUCKLED	660.00	660.00
4	FRONT BUMPER CLIPS @\$4.00	NECESSARY	16.00	16.00
1	REAR TAILGATE	BENT	1,648.00	1,648.00
1	REAR BUMPER	BUCKLED	660.00	660.00
1	REAR WINDSCREEN C/W MOULDINGS	MTG NECESSARY	1,351.00	1,351.00
	LESS 20% DISCOUNT		-	-1,218.56
			10,414.80	4,874.24
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SOLAR FILM + INSTALLATION (SN)	NOT NECESSARY	350.00	-
4	REVERSING SENSOR WITH INSTALLATION (SN)	DENTED	280.00	280.00
1	FRONT NUMBER PLATE (SN)	CRACKED	70.00	45.00
			700.00	325.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE + REFIX REAR WINDSCREEN.		160.00	120.00
	TO SUPPLY SEALANT.		40.00	40.00
	TO DISMANTLE + REFIX REAR TAILGATE SPOILER + REVERSING CAMERA, ETC.		150.00	120.00
	TO STRAIGHTEN FRONT BODY, TO KNOCK DENTS ON FRONT SUPPORT PANEL, FRONT FENDER LH & RH AND RENEW OF PARTS.		550.00	400.00
	TO STRAIGHTEN REAR BODY, TO DISMANTLE + RENEW PARTS.		500.00	400.00
	TO SPRAY PAINT (FRONT PORTION).		800.00	600.00

Report Ref No. CS/GAI22009829/Kny3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT (REAR PORTION).		600.00	400.00
			2,800.00	2,080.00
GRAND TOTAL			13,914.80	7,279.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CS/GAI22009829/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.