

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22005401/Tqce2	
	8 SHENTON WAY SINGAPORE 0688		Date:	29/07/2022		
	ATTN: KHOR SAW	THENG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 7969J	Veh. Inspected		FBT 15D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M043FX	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		07/06/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	YAMAHA T155	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	RLCUG1610MY001396	Colour		GREY	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	90/80 R17	PIRELLI		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70 R17	PIRELLI		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	03/06/2022	Inspect Date /	Time	08/06/2022 (01:15 PM)	
	Survey held at	ADVANCE REPUBLIC PTE LTD				
		BLK 68 KAKI BUKIT AVE 6 #04-06 SINGAPORE 417896				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22005401/Tqce2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser