

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009837/RQY3M4**Date:** 13/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00003252200

Claimant Vehicle No : SNA5215T **Insured Vehicle No :** CB7503Z

Date of Loss: 03/10/2022 Nature of Claim: TP Claim No: SNM22D207066/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA5215T**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G92130

Reg. Date: 28/06/2021 (Man. Year: 2020) Chassis No: JTDKB3FU903091914

Colour: Grey Odometer: 134874 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm

Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	72,498.88	23,192.55	49,306.33	68.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,280.00	4,500.00	8,780.00	66.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	85,778.88	27,692.55	58,086.33	67.72
Approved Total (Overridden) (S\$)		19,400.00		
(S\$)	85,778.88	19,400.00	66,378.88	77.38
+ GST 8.00/8.00% (S\$)	6,862.31	1,552.00	5,310.31	77.38
Nett Amount (S\$)	92,641.19	20,952.00	71,689.19	77.38

INSPECTION

Date of Assignment: 04/10/2022

Date Inspected: 05/10/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA5215T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	989.00 FL	*989.00 FL
2	1		*BONNET HINGES	Bent	112.00 FL	*112.00 FL
3	1		*BONNET LOCK	Bent	312.00 FL	*312.00 FL
4	1		*BONNET INSULATOR	Deformed	324.00 FL	*324.00 FL
5	1		*BONNET RUBBER	Necessary	25.00 FL	*25.00 FL
6	1		*FRONT BUMPER	Torn	798.00 FL	*798.00 FL
7	1		*FRONT BUMPER LOWER	Cracked	651.00 FL	*651.00 FL
8	1		*FRONT BUMPER LOGO	Cracked	68.00 FL	*68.00 FL
9	1		*FRONT BUMPER SIDE RETAINER	N/S Necessary	116.00 FL	*58.00 FL
10	2		*FRONT BUMPER BRACKET	Not Necessary	104.00 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Cracked	215.00 FL	*215.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	412.00 FL	*- FL
13	2		*FRONT BUMPER FOGLAMP	Not Necessary	624.00 FL	*- FL
14	1		*FRONT BUMPER FOGLAMP COVER	N/S Scratched	224.00 FL	*112.00 FL
15	1		*FRONT BUMPER TOWING COVER	N/S Missing	84.00 FL	*42.00 FL
16	1		*FRONT BUMPER LOWER GRILLE CENTRE	Not Necessary	259.00 FL	*- FL
17	1		*FRONT BUMPER UNDER COVER	Not Necessary	312.00 FL	*- FL
18	1		*FRONT BUMPER TOP RUBBER	Cut	68.00 FL	*68.00 FL
19	1		*FRONT GRILLE	Cracked	498.00 FL	*498.00 FL
20	1		*FRONT SUPPORT PANEL	Bent	898.00 FL	*898.00 FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Cut	184.00 FL	*184.00 FL
22	2		*HEADLAMP	Cracked	5,182.00 FL	*5,182.00 FL
23	2		*HEADLAMP LOWER BRACKET	Not Necessary	84.00 FL	*- FL
24	1		*FRONT WIPER GARNISH (CENTRE)	Not Necessary	311.00 FL	*- FL
25	2		*FRONT WIPER GARNISH (SIDE)	Not Necessary	124.00 FL	*- FL
26	1		*HYBRID BATTERY	Not Necessary	9,857.00 FL	*- FL
27	1		*HYBRID BATTERY BRACKET	Not Necessary	357.00 FL	*- FL
28	1		*AIR CLEANER HOUSING	Cut	698.00 FL	*698.00 FL
29	1		*AIR CLEANER AIR DUCT	Not Necessary	187.00 FL	*- FL
30	1		*ENGINE TOP COVER	Not Necessary	287.00 FL	*- FL
31	2		*FRONT ENGINE MOUNTING	Not Necessary	1,224.00 FL	*- FL
32	1		*FRONT EXHAUST MANIFOLD	Not Necessary	1,025.00 FL	*- FL
33	2		*FRONT CHASSIS EXTENSION	Not Necessary	574.00 FL	*- FL
34	1		*FRONT DASHBOARD	Not Necessary	2,985.00 FL	*- FL
35	1		*FRONT DASHBOARD AIRBAG	Not Necessary	698.00 FL	*- FL
36	1		*FRONT INTERIOR VIEW MIRROR	Not Necessary	298.00 FL	*- FL
37	1		*ROOF LINING	Not Necessary	2,874.00 FL	*- FL
38	2		*ROOF SIDE AIR BAG	Not Necessary	2,050.00 FL	*- FL
39	1		*STEERING AIRBAG	Not Necessary	698.00 FL	*- FL
40	2		*FRONT SEAT BELT	Not Necessary	1,978.00 FL	*- FL
41	2		*FRONT SEAT AIRBAG	Not Necessary	1,396.00 FL	*- FL
42	2		*FRONT SEAT COVER	Not Necessary	1,596.00 FL	*- FL
43	2		*FRONT DOOR CENTRE PILLAR INNER GARNISH LOWER	Not Necessary	296.00 FL	*- FL
44	1		*FUSE BOX	Not Necessary	878.00 FL	*- FL
45	1		*FRONT WIRE HARNESS	Not Necessary	1,125.00 FL	*- FL
46	1		*BATTERY TRAY	Not Necessary	159.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BATTERY BRACKET	Not Necessary	42.00 FL	*- FL
48	1		*ALTERNATOR	Not Necessary	1,324.00 FL	*- FL
49	1		*STARTER MOTOR	Not Necessary	1,211.00 FL	*- FL
50	1		*ENGINE TOP COVER	Not Necessary	258.00 FL	*- FL
51	1		*SET ENGINE MOUNTING	Not Necessary	2,120.00 FL	*- FL
52	1		*AIRCON COMPRESSOR	Not Necessary	1,327.00 FL	*- FL
53	1		*AIRCON CONDENSER	Bent	1,157.00 FL	*1,157.00 FL
54	1		*AIRCON CONDENSER SUCTION PIPE	Not Necessary	355.00 FL	*- FL
55	1		*AIRCON CONDENSER DISCHARGE PIPE	Not Necessary	341.00 FL	*- FL
56	2		*AIRCON CONDENSER AIR ARCH GARNISH	Not Necessary	224.00 FL	*- FL
57	1		*RADIATOR	Bent	1,287.00 FL	*1,287.00 FL
58	1		*RADIATOR COWLING	Not Necessary	421.00 FL	*- FL
59	1		*RADIATOR FAN MOTOR	Not Necessary	598.00 FL	*- FL
60	1		*RADIATOR FAN BLADE	Not Necessary	221.00 FL	*- FL
61	1		*RADIATOR COOLANT RESERVIOR	Not Necessary	212.00 FL	*- FL
62	1		*HYBRID COOLER	Not Necessary	1,251.00 FL	*- FL
63	1		*FRONT WINDSCREEN GLASS	Not Necessary	1,359.00 FL	*- FL
64	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	212.00 FL	*- FL
65	1		*FRONT WIPER GARNISH CENTRE	Not Necessary	298.00 FL	*- FL
66	2		*FRONT WIPER GARNISH SIDE	Not Necessary	104.00 FL	*- FL
67	1		*WIPER WASHER TANK	Not Necessary	358.00 FL	*- FL
68	1		*FRONT FENDER	N/S Bent	1,022.00 FL	*521.00 FL
69	2		*FRONT FENDER WHEEL HOUSING	Not Necessary	2,050.00 FL	*- FL
70	2		*FRONT FENDER EMBLEMHYBRID	Necessary	104.00 FL	*104.00 FL
71	2		*FRONT FENDER COWLING	Not Necessary	396.00 FL	*- FL
72	2		*FRONT FENDER QUARTER GLASS MOULDING	Not Necessary	318.00 FL	*- FL
73	1		*FRONT DOOR LH	Repair	1,259.00 FL	*- FL
74	1		*TAILGATE	Bent	1,359.00 FL	*1,359.00 FL
75	1		*TAILGATE LAMP LH	Cracked	918.00 FL	*918.00 FL
76	1		*TAILGATE WEATHERSTRIP	Necessary	212.00 FL	*212.00 FL
77	1		*TAILGATE OUTER GARNISH	Cracked	521.00 FL	*521.00 FL
78	1		*TAILGATE LOGO	Necessary	95.50 FL	*95.50 FL
79	1		*TAILGATE EMBLEM PRIUS T	Necessary	89.40 FL	*89.40 FL
80	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*82.30 FL
81	1		*TAILGATE ABSORBER	N/S Bent	302.00 FL	*251.00 FL
82	1		*TAILGATE LOWER GLASS	Broken	798.00 FL	*798.00 FL
83	1		*TAILGATE LOWER GLASS MOULDING	Necessary	159.00 FL	*159.00 FL
84	1		*TAILGATE TOP SPOILER	Cracked	1,125.00 FL	*1,125.00 FL
85	1		*TAILGATE DETECTOR	Not Necessary	321.00 FL	*- FL
86	1		*TAILGATE LOCK	Cut	312.00 FL	*312.00 FL
87	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
88	1		*TAILGATE INNER TRIM BOARD	Cracked	459.00 FL	*459.00 FL
89	1		*TAILGATE INNER HANDLE	Cracked	38.00 FL	*38.00 FL
90	1		*REAR BUMPER	Torn	658.00 FL	*658.00 FL
91	1		*REAR BUMPER SIDE RETAINER	N/S Necessary	224.00 FL	*112.00 FL
92	1		*REAR BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
93	1		*REAR BUMPER TOP LAMP LH	Cracked	412.00 FL	*412.00 FL
94	2		*REAR BUMPER BRACKET	Not Necessary	228.00 FL	*- FL
95	1		*REAR BUMPER LIP	Deformed	728.90 FL	*728.90 FL
96	1		*REAR BUMPER REFLECTOR	N/S Cracked	136.00 FL	*68.00 FL
97	1		*REAR BUMPER UNDER COVER LH	Cracked	321.00 FL	*321.00 FL
98	1		*REAR BUMPER UNDER COVER RH	Not Necessary	251.00 FL	*- FL
99	1		*REAR FENDER	N/S Buckled	1,796.00 FL	*898.00 FL
100	1		*REAR FENDER WHEEL HOUSING LH	Buckled	1,025.00 FL	*1,025.00 FL
101	1		*REAR FENDER COWLING	N/S Deformed	396.40 FL	*198.20 FL
102	1		*REAR FENDER INNER TRIM	N/S Deformed	1,218.00 FL	*612.00 FL
103	1		*TAILLAMP	N/S Cracked	1,162.00 FL	*581.00 FL
104	1		*TAILLAMP LOWER BRACKET	N/S Cracked	164.00 FL	*82.00 FL
105	1		*REAR END PANEL	Bent	612.00 FL	*612.00 FL
106	1		*REAR END PANEL TOP GARNISH	Deformed	212.00 FL	*212.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*REAR FLOOR PANEL	Repair	1,151.00 FL	*- FL
108	1		*REAR FLOOR PANEL TOP BOARD	Deformed	398.00 FL	*398.00 FL
109	1		*REAR FLOOR PANEL SIDE LH	Bent	352.00 FL	*352.00 FL
110	1		*REAR FLOOR PANEL TOP SIDE SPONGE	N/S Deformed	624.00 FL	*312.00 FL
111	1		*REAR FLOOR PANEL TOP CENTRE SPONGE	Not Necessary	522.00 FL	*- FL
112	1		*REAR DOOR LOCK LH	Not Necessary	321.00 FL	*- FL
113	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	212.00 FL	*- FL
114	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	312.00 FL	*- FL
115	1		*TAILGATE TOP GARNISH	Cracked	656.90 FL	*656.90 FL
116	1		*TAILGATE LOWER GLASS INNER TRIM	Deformed	27.60 FL	*27.60 FL
117	1		*REAR FENDER AIR VENT	Deformed	65.00 FL	*65.00 FL
118	1		*FENDER TOP GARNISH	Missing	301.10 FL	*301.10 FL
119	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 FS	*30.00 FS
120	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*35.00 FS
121	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
122	1		*SET FRONT FENDER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
123	1		*SET FRONT SUPPORT TOP GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
124	1		*BATTERY	Cut	300.00 FS	*150.00 FS
125	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
126	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
127	1		*GEARBOX OIL	Not Necessary	150.00 FS	*- FS
128	1		*FRONT DASHBOARD CLIP	Not Necessary	80.00 FS	*- FS
129	1		*ROOF LINING CLIP	Not Necessary	100.00 FS	*- FS
130	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
131	1		*FRONT SPORTS RIM LH	Not Necessary	800.00 FS	*- FS
132	1		*FRONT TYRE LH	Not Necessary	180.00 FS	*- FS
133	1		*INTERIOR CAMERA	Not Necessary	400.00 FS	*- FS
134	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
135	1		*COOLANT	Necessary	30.00 FS	*30.00 FS
136	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
137	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*40.00 FS
138	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
139	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
140	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
141	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
142	1		*REAR NUMBER PLATE GARNISH	Not Necessary	50.00 FS	*- FS
143	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
144	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
145	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*40.00 FS
146	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	89,673.60	30,668.40
- List Item Discount on L Items 20.00/25.00% (\$)	17,174.72	7,475.85
Total Parts (\$)	72,498.88	23,192.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	150.00	60.00
2	REMOVE AND REFIR AIRCON AND RADIATOR	New	150.00	100.00
3	REALIGN HEADLAMP	New	50.00	0.00
4	RESET HYBRID BATTERY CODE	New	300.00	0.00
5	REMOVE AND REFIR ENGINE ASSEMBLY	New	500.00	0.00
6	REALIGN FRONT CHASSIS	New	1,200.00	0.00
7	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	150.00	0.00
8	TO REMOVE AND REFIT ENGINE ASSEMBLY	New	800.00	0.00
9	REMOVE AND RENEW GEARBOX ASSEMBLY	New	500.00	0.00
10	REMOVE AND RENEW FRONT DASHBOARD	New	400.00	0.00
11	REMOVE AND RENEW FRONT SEAT BELT	New	300.00	0.00
12	REMOVE AND RENEW STEERING AIRBAG	New	150.00	0.00
13	REMOVE AND RENEW ROOF LINING	New	400.00	0.00
14	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	60.00
15	TO REMOVE AND REFIT REAR GLASS	New	150.00	80.00
16	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	New	200.00	60.00
17	REMOVE AND RENEW TAILGATE MECHANISM	New	80.00	40.00
18	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	0.00
19	REMOVE AND RENEW FRONT UNDERCARRIAGE	New	600.00	0.00
20	CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
21	TO RESPRAY UNDERCOATING	New	150.00	0.00
22	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	100.00
23	SPRAY PAINTING ON AFFECTED AREAS	New	3,200.00	2,000.00
24	PANEL BEATING ON AFFECTED AREAS	New	3,200.00	2,000.00
Gross Labour Cost (S\$)			13,280.00	4,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >