



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6827Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	SEALANT - LH FRT DOOR (SN)	NECESSARY	60.00	60.00
1	LH FRT TYRE (SN) (60%)	PUNCTURE	680.00	408.00
1	COVER, FR BUMPER (SN)	DEEP CUT	811.30	811.30
1	RETAINER, FR BUMPER (SN)	NECESSARY	115.20	115.20
1	PANEL, FR FENDER, LH (SN)	DENTED	1,446.30	1,446.30
1	LINER, FR FENDER, LH (SN)	* CHECK	522.50	-
10	CLIP (SN)	NECESSARY	39.00	39.00
1	PANEL SUB-ASSY, FR (SN)	DENTED	1,881.30	1,881.30
1	TAPE, BLACK OUT (SN)	NECESSARY	58.20	58.20
1	TAPE, BLACK OUT FR (SN)	NECESSARY	42.20	42.20
1	TAPE, BLACK OUT FR (SN)	NECESSARY	26.40	26.40
1	UNIT, HEADLAMP (SN)	* CHECK	7,269.60	-
1	REINFORCEMENT, FR (SN)	* CHECK	69.80	-
1	WHEEL, DISC (SN)	WARPED	2,700.60	2,700.60
1	MOULDING ASSY, BODY (SN)	* CHECK	734.20	-
1	ABSORBER ASSY (SN)	* CHECK	683.80	-
1	LINK ASSY, FR (SN)	* CHECK	178.40	-
1	ARM SUB-ASSY (SN)	* CHECK	881.00	-
1	JOINT ASSY, LWR BALL (SN)	* CHECK	286.00	-
1	KNUCKLE, STEERING (SN)	* CHECK	795.50	-
1	HUB & BEARING ASSY (SN)	* CHECK	722.10	-
			20,033.40	7,618.50
<u>LABOUR</u>				
CHECK LIGHTING & WIRING SYSTEM.			122.40	122.40
TRANSFER & INSTALL COMPONENTS TO NEW DOOR.			360.00	360.00
REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING.			72.00	72.00
REPLACE LH FRT SUSPENSION SYSTEM.		* CHECK	720.00	-
CONDUCT FULL WHEEL ALIGNMENT.			180.00	180.00

Report Ref No. CS/FCI22009848/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR.		180.00	180.00
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPLACE LH FRT ACCIDENT DAMAGED PARTS		2,880.00	1,440.00
	STRAIGHTEN & ALIGN LH FRT ACCIDENT AFFECTED AREAS.			
	RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS.		2,360.00	1,770.00
			7,054.40	4,304.40
GRAND TOTAL			27,087.80	11,922.90
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$12,862.90 NETT)				11,922.90

Report Ref No. CS/FCI22009848/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.