



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22009848/Uqy3e2 Date: 13/07/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 3436H	Veh. Inspected	SMV 6827Y
Policy No.		Coverage (\$)	0.00
Claim No.	D22003107MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	05/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER M GRADE (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTEZB3GH60J005644	Colour	WHITE
Odometer	35293 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	TOYO	6 mm
L/H Front Tyre	235/55 R18	TOYO	6 mm
R/H Rear Tyre	235/55 R18	TOYO	6 mm
L/H Rear Tyre	235/55 R18	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/10/2022	Inspection Date	05/10/2022
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	