

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009852/AGQY3M4**Date:** 26/04/2023**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001440400

Claimant Vehicle No : SNG6585L**Insured Vehicle No :** SLR3185T

Date of Loss: 30/09/2022

Nature of Claim: TP

Claim No: 286755

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNG6585L**

Make & Model: SUBARU FORESTER, 2.0 I-L EYESIGHT AWD CVT (A)

Engine No: FB20YN71804

Reg. Date: 25/08/2022 (Man. Year: 2021)

Chassis No: JF1SK7KL5MG060649

Colour: Red

Odometer: 9748 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R17

Rear Tyre Size: 225/60R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,922.60	4,466.96	4,455.64	49.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,130.00	1,500.00	41.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,552.60	6,596.96	5,955.64	47.45
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	12,552.60	5,200.00	7,352.60	58.57

INSPECTION

Date of Assignment: 05/10/2022

Date Inspected: 10/10/2022 Inspected At:

ADVANCE AUTO GARAGE
23 KAKI BUKIT AVENUE 4
#04-01 AAS KAKI BUKIT CENTRE, SINGAPORE
415933

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG6585L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	682.40 F	*682.40 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	72.40 F	*- FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	32.90 F	*- FL
4	1		*REAR BUMPER REFLECTOR 2PIECES	N/s Cracked	85.60 F	*42.80 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	396.80 F	*396.80 FL
6	1		*REAR END PANEL	Dented	468.40 F	*468.40 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	142.90 F	*142.90 FL
8	1		*TAILLAMP 2PIECES	N/s Cut	950.20 F	*475.10 FL
9	1		*TAILGATE	Distorted	1,390.40 F	*1,245.00 FL
10	1		*TAILGATE LOCK	Damaged	285.90 F	*285.90 FL
11	1		*TAILGATE WEATHERSTRIPE	Not Necessary	189.90 F	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed	289.50 F	*289.50 FL
13	1		*TAILGATE REFLECTOR 2PIECES	N/s Cracked	808.20 F	*351.00 FL
14	1		*TAILGATE GLASS MOULDING	Necessary	149.40 F	*149.40 FL
15	1		*SUBARU WORDING	Necessary	58.90 F	*58.90 FL
16	1		*4WD WORDING	Necessary	52.50 F	*52.50 FL
17	1		*FORESTER WORDING	Necessary	59.40 F	*59.40 FL
18	1		*EMBLEM	Necessary	48.20 F	*48.20 FL
19	1		*REAR FENDER INNER TRIM BOARD 2PIECES	N/s Cracked	596.00 F	*298.00 FL
20	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	320.40 F	*- FL
21	1		*REAR EXHAUST PIPE	Not Necessary	694.20 F	*- FL
22	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.20 F	*- FL
23	1		*REAR EXHAUST PIPE GASKET	Not Necessary	32.90 F	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
25	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
26	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
29	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
30	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
32	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	8,922.60 5,476.20
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 1,009.24
					Total Parts (\$\$)	8,922.60 4,466.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	900.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO APPLY TUFF COAT	New	150.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,630.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >