11/30/22, 2:52 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009854/ENY3Q2

30/11/2022 Date:

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00091132200

Claimant Vehicle

SMY7405J

Insured Vehicle SMT9545B

No:

Date of Loss: 04/10/2022 Nature of Claim: TP Claim

38061 km

SNM22D207112/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMY7405J Reg No:

G4FGKH739951 Make & Model: KIA CERATO, 1.6 SUNROOF (A) Engine No: Reg. Date: 24/03/2021 (Man. Year: 2020) Chassis No: KNAF5416MM5095937

Colour: Blue Odometer:

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16 Front Left Side: Rear Left Side: Michelin 4 mm Michelin 4 mm Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,836.00	1,522.00	314.00	17.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	2,280.00	1,930.00	45.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,046.00	3,802.00	2,244.00	37.12
+ GST 7.00/7.00% (S\$)	423.22	266.14	157.08	37.12
Nett Amount (S\$)	6.469.22	4,068.14	2,401.08	37.12

INSPECTION

Date of Assignment: 05/10/2022

Cycle & Carriage KIA Pte Ltd (Pandan Gardens) Date Inspected: 03/11/2022 Inspected At: 209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts: 143 KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY7405J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
1		*PANEL ASSY -FRONT DOOR ,RH	Dented	1,377.00 FS	*1,377.00 FS
1		*HANDLE ASSY -DOOR OUTSIDE ,RH	Repair	164.00 FS	*-FS
1		*MOULDING ASSY -FRT DR FRAME ,RH	Necessary	72.00 FS	*72.00 FS
1		*W/STRIP ASSY -FR DR BELT O/S RH	Not Necessary	80.00 FS	*-FS
1		*BLACK TAPE -FR DR RR ,RH	Necessary	13.00 FS	*13.00 FS
ınchise	part. S=SpcN	ett.	_		
			Total Parts (S\$)	1,836.00	1,522.00
	1 1 1 1 1 1 1	1 1 1 1 1 1 1	1 *SUNDRIES 1 *BODY PNL SEALANT 1 *PANEL ASSY -FRONT DOOR ,RH 1 *HANDLE ASSY -DOOR OUTSIDE ,RH 1 *MOULDING ASSY -FRT DR FRAME ,RH 1 *W/STRIP ASSY -FR DR BELT O/S RH	1 *SUNDRIES Necessary 1 *BODY PNL SEALANT Necessary 1 *PANEL ASSY -FRONT DOOR ,RH Dented 1 *HANDLE ASSY -DOOR OUTSIDE ,RH Repair 1 *MOULDING ASSY -FRT DR FRAME ,RH Necessary 1 *W/STRIP ASSY -FR DR BELT O/S RH Not Necessary 1 *BLACK TAPE -FR DR RR ,RH Necessary	1 *SUNDRIES Necessary 50.00 FS 1 *BODY PNL SEALANT Necessary 80.00 FS 1 *PANEL ASSY -FRONT DOOR ,RH Dented 1,377.00 FS 1 *HANDLE ASSY -DOOR OUTSIDE ,RH Repair 164.00 FS 1 *MOULDING ASSY -FRT DR FRAME ,RH Necessary 72.00 FS 1 *W/STRIP ASSY -FR DR BELT O/S RH Not Necessary 80.00 FS 1 *BLACK TAPE -FR DR RR ,RH Necessary 13.00 FS

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REPLACE FR DOOR PANEL & AFFECTED AREA	New	1,920.00	640.00
2	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
3	CHECK WIRING AND DOOR HANDLE FUNCTION	New	80.00	80.00
4	SPRAY PAINT FRONT RIGHT DOOR PANEL ,LOWER SKIRT, FRONT RIGHT PANEL	New	1,650.00	1,100.00
5	REMOVE & REFIT ALL RHF DOOR COMPONENT	New	280.00	180.00
	Gross Labou	ır Cost (S\$)	4,210.00	2,280.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >