

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22009857/UPA3Q2
Date: 17/01/2023

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_02
Claimant Vehicle No :	SFW9905M	Insured Vehicle No :	GBK7612G
Date of Loss:	01/10/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0005541

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFW9905M		
Make & Model:	MERCEDES-BENZ E300 AMG LINE (R19 LED), 2.0 (A)	Engine No:	26492030384689
Reg. Date:	29/06/2021 (Man. Year: 2021)	Chassis No:	W1K2384832F161696
Colour:	White	Odometer:	12839 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	275/30 R20
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,535.19	7,693.57	4,841.62	38.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	4,250.00	1,570.00	2,680.00	63.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,796.19	9,274.57	7,521.62	44.78
Approved Total (Overridden) (S\$)		7,400.00		
	(S\$)	16,796.19	7,400.00	9,396.19
	+ GST 7.00/7.00% (S\$)	1,175.73	518.00	657.73
	Nett Amount (S\$)	17,971.92	7,918.00	10,053.92
	+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00	
	+ Doc/Search Fee (S\$)		7.45	
	Nett Liability (S\$)		8,425.45	

INSPECTION

Date of Assignment:	06/10/2022	Present Location:	Joo Hak Kee Auto Pte Ltd (HQ)
Date Inspected:	05/10/2022	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2022)
Parts: 143	MERCEDES-BENZ E300 AMG LINE (R19 LED) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFW9905M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper	Dented / Torn	2,379.98 FL	*2,379.98 FL
2	1		*Rear bumper lower	Dented / Torn	601.83 FL	*601.83 FL
3	1		*Rear Bumper Lower Moulding	Cracked	356.77 FL	*356.77 FL
4	1		*Rear Bumper Tow Eye Cover	Not Necessary	87.27 FL	*- FL
5	1		*Rear Bumper Reinforcement	Bent	938.87 FL	*938.87 FL
6	1		*Rear Bumper Upper Carrier	Cracked	118.97 FL	*118.97 FL
7	1		*Rear Bumper Lower Carrier	Not Necessary	95.87 FL	*- FL
8	1		*Rear Bumper Bracket LH	Cracked	119.42 FL	*119.42 FL
9	1		*Rear Bumper Bracket RH	Cracked	119.53 FL	*119.53 FL
10	1		*Rear Bumper Side Retainer LH	Not Necessary	116.51 FL	*- FL
11	1		*Rear Bumper Side Retainer RH	Not Necessary	116.51 FL	*- FL
12	1		*Rear Bumper Side Trim LH	Not Necessary	136.35 FL	*- FL
13	1		*Rear Bumper Side Trim RH	Not Necessary	136.35 FL	*- FL
14	1		*Rear Bumper Reflector LH	Cracked	45.09 FL	*45.09 FL
15	1		*Rear Bumper Reflector RH	Not Necessary	45.09 FL	*- FL
16	1		*Rear Bumper Exhaust Chrome LH	Not Necessary	475.44 FL	*- FL
17	1		*Rear Bumper Exhaust Chrome RH	Not Necessary	475.44 FL	*- FL
18	1		*Rear Bumper PDC Sensor	Shorted	333.63 FL	*333.63 FL
19	1		*Rear Bumper Wire Harness	Not Necessary	274.29 FL	*- FL
20	1		*Rear Foot Kick Sensor Upper	Not Necessary	181.82 FL	*- FL
21	1		*Rear Foot Kick Sensor Lower	Not Necessary	181.82 FL	*- FL
22	1		*Rear Foot Kick Sensor Module	Not Necessary	187.17 FL	*- FL
23	1		*Rear License Lamp	Not Necessary	32.59 FL	*- FL
24	1		*Trunk Lid	Dented	3,428.32 FL	*3,428.32 FL
25	1		*Trunk Lid Lock	Not Necessary	366.91 FL	*- FL
26	1		*Trunk Lid Lock Striker	Not Necessary	39.49 FL	*- FL
27	1		*Trunk Lid Opener Switch	Not Necessary	206.36 FL	*- FL
28	1		*Trunk Lid Weatherstrip	Not Necessary	318.89 FL	*- FL
29	1		*Trunk Lid Logo	Serviceable	196.85 FL	*- FL
30	1		*Trunk Lid E300 Emblem	Necessary	206.36 FL	*106.00 FL
31	1		*Trunk Lid Lamp LH	Not Necessary	804.10 FL	*- FL
32	1		*Trunk Lid Lamp RH	Not Necessary	804.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	13,927.99	8,548.41
- List Item Discount on L Items 10.00/10.00% (\$)	1,392.80	854.84
Total Parts (\$)	12,535.19	7,693.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Panel Beat On Necessary Accident Parts	New	1,800.00	600.00
2	To Sand Down, Putty & Spray Painting On Necessary Accident Damaged Parts	New	1,700.00	800.00
3	To Diagnose and Calibrate Parktronic	New	350.00	150.00
4	To Diagnose and Reset Convertible Soft Cover Roof	New	350.00	0.00
5	To Check Wiring	New	50.00	20.00
			Gross Labour Cost (\$)	4,250.00
				1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >