

Vehicle Damage Assessment Report for [SFW9905M]

Estimate Created: 06/10/2022 10:29 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 30/10/2022 10:32 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

| | | | |
|-------------------|------------------------------|------------------|-----------------|
| Insurance Company | III | Claim Number | MFL2022D0005541 |
| Claim Type | TP | | |
| Workshop | LKK_Auto_Consultants_Pte_Ltd | Reference Number | |

Vehicle Information

| | | | |
|----------------------|---------------|--------------------|---------|
| Brand | Mercedes-Benz | Model | E-Class |
| Engine Type | | | |
| License Plate Number | SFW9905M | VIN (or Chassis #) | |

Vehicle Condition

| | | | |
|-----------------|--|-----------------|---------|
| Damaged Diagram | | Odometer | 0.00 Km |
| | | Tyres Condition | |
| | | Front Left | mm |
| | | Front Right | mm |
| | | Rear Left | mm |
| | | Rear Right | mm |

Comments

- Final review base on information provided by LKK: Concluded the cost of repair at lump sum \$7,400.00 with 5 days for repair

Insurlogic 3 (30/10/2022 10:31)

Parts

| Description | Number/Type | Qty | Cost | Markup/Disc.% | Sum |
|----------------------------|-------------|-----|---------|---------------|----------|
| Rear Bumper | | 1 | 2379.98 | -10.00 % | 2,141.98 |
| Rear Bumper Lower | | 1 | 601.83 | -10.00 % | 541.65 |
| Rear Bumper Lower Moulding | | 1 | 356.77 | -10.00 % | 321.09 |
| Rear Bumper Reinforcement | | 1 | 938.87 | -10.00 % | 844.98 |
| Rear Bumper Upper Carrier | | 1 | 118.97 | -10.00 % | 107.07 |
| Rear Bumper Bracket LH | | 1 | 119.42 | -10.00 % | 107.48 |
| Rear Bumper Bracket RH | | 1 | 119.42 | -10.00 % | 107.48 |
| Rear Bumper Reflector LH | | 1 | 45.09 | -10.00 % | 40.58 |
| Rear Bumper PDC Sensor | | 1 | 333.63 | -10.00 % | 300.27 |
| Trunk Lid | | 1 | 3428.32 | -10.00 % | 3,085.49 |
| Trunk Lid E300 Emblem | | 1 | 106.00 | -10.00 % | 95.40 |
| Parts Subtotal | | | | | 7,693.47 |

Materials

| Description | Number/Type | Qty | Cost | Markup/Disc.% | Sum |
|--------------------|-------------|-----|-------|---------------|-------|
| OD/TP case | | 1.0 | 11.00 | 0.00 % | 11.00 |
| Materials Subtotal | | | | | 11.00 |

Labor**Replace/RnR**

| Description | Type | Cost | Markup/Disc % | Price |
|--|------|--------|---------------|--------|
| To remove & refix the accident affected area | RnR | 600.00 | 0.00 % | 600.00 |
| To disgnostic | RnR | 150.00 | 0.00 % | 150.00 |
| To check wiring | RnR | 20.00 | 0.00 % | 20.00 |

Paint

| Description | Paint Type | Cost | Markup/Disc % | Price |
|--|------------|--------|---------------|--------|
| To spray paint on the accident affected area | Full spray | 800.00 | 0.00 % | 800.00 |

Labor Rate S\$ 50 / Hour

General Labor Subtotal 770.00

Paint Labor Subtotal 800.00

Labor Subtotal 1,570.00

Summary

| | |
|-----------------------|-----------------|
| Repair Cost | 9,274.47 |
| Discount(20 %) | (1,874.47) |
| | 7,400.00 |
| Excess | (0.00) |
| GST(0.00 %) | 0.00 |
| Grand Subtotal | 7,400.00 |