

**Joo Hak Kee Auto Pte Ltd** (Co.Reg.No:201300082W)

Blk 3007 Ubi Road 1, #01-406

Singapore 408701

Tel: 67431913 Fax: 67435234 Email: admin@jhk.com.sg;yvonneang@jhk.com.sg

**TP INSURER: India International Insurance Pte Ltd (HQ)**

a

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D19MFL0005549_02	Date of Loss:	01/10/2022
Vehicle Reg. No.:	<b>SFW9905M</b>	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHEN YONG		

Make/Model:	MERCEDES-BENZ E300 AMG LINE (R19 LED), 2.0 (A)	Vehicle Reg. Date:	29/06/2021
Vehicle Colour:	WHITE	Chassis No:	W1K2384832F161696
Engine No:	26492030384689		
Odometer:	0 KM		

Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	10.00 %		

Total Loss? **NO**

Est. Duration of Repair (day) 14

*not Authorized her works 5/10/22*  
*2/5 \$7600*  
*plz photo before painting 5 days*

Present Location: JOO HAK KEE AUTO PTE LTD (HQ)

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**COST OF CLAIMS**

	<b>Amount</b>
Parts	12,535.19
Miscellaneous Items	11.00
Labour	4,250.00
Paintwork Labour	0.00
Towing	0.00

<b>Gross Total (S\$)</b>	<b>16,796.19</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,175.73</b>
<b>Nett Amount (S\$)</b>	<b>17,971.92</b>

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Oct 2022)

Parts: 143 MERCEDES-BENZ E300 AMG LINE (R19 LED) 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFW9905M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper <i>DD/To, n</i>	10.00	0.00	*2,379.98 FL ✓
2	1		*Rear bumper lower <i>DD/To, n</i>	10.00	0.00	*601.83 FL ✓
3	1		*Rear Bumper Lower Moulding <i>cn</i>	10.00	0.00	*356.77 FL ?
4	1		*Rear Bumper Tow Eye Cover <i>11</i>	10.00	0.00	*87.27 FL X
5	1		*Rear Bumper Reinforcement <i>5enf</i>	10.00	0.00	*938.87 FL ✓
6	1		*Rear Bumper Upper Carrier <i>cn</i>	10.00	0.00	*118.97 FL ✓
7	1		*Rear Bumper Lower Carrier <i>11</i>	10.00	0.00	*95.87 FL X
8	1		*Rear Bumper Bracket LH <i>cn</i>	10.00	0.00	*119.42 FL ✓
9	1		*Rear Bumper Bracket RH <i>cn</i>	10.00	0.00	*119.53 FL ✓
10	1		*Rear Bumper Side Retainer LH <i>11</i>	10.00	0.00	*116.51 FL X
11	1		*Rear Bumper Side Retainer RH <i>11</i>	10.00	0.00	*116.51 FL X
12	1		*Rear Bumper Side Trim LH <i>11</i>	10.00	0.00	*136.35 FL X
13	1		*Rear Bumper Side Trim RH <i>11</i>	10.00	0.00	*136.35 FL X
14	1		*Rear Bumper Reflector LH <i>cn</i>	10.00	0.00	*45.09 FL ✓
15	1		*Rear Bumper Reflector RH <i>11</i>	10.00	0.00	*45.09 FL X
16	1		*Rear Bumper Exhaust Chrome LH <i>11</i>	10.00	0.00	*475.44 FL X
17	1		*Rear Bumper Exhaust Chrome RH <i>11</i>	10.00	0.00	*475.44 FL X
18	1		*Rear Bumper PDC Sensor <i>shudd</i>	10.00	0.00	*333.63 FL ✓
19	1		*Rear Bumper Wire Harness <i>11</i>	10.00	0.00	*274.29 FL X
20	1		*Rear Foot Kick Sensor Upper <i>11</i>	10.00	0.00	*181.82 FL A
21	1		*Rear Foot Kick Sensor Lower <i>11</i>	10.00	0.00	*181.82 FL A
22	1		*Rear Foot Kick Sensor Module <i>11</i>	10.00	0.00	*187.17 FL X
23	1		*Rear License Lamp <i>11</i>	10.00	0.00	*32.59 FL X
24	1		*Trunk Lid <i>DD</i>	10.00	0.00	*3,428.32 FL ✓
25	1		*Trunk Lid Lock <i>11</i>	10.00	0.00	*366.91 FL X
26	1		*Trunk Lid Lock Striker <i>11</i>	10.00	0.00	*39.49 FL X
27	1		*Trunk Lid Opener Switch <i>11</i>	10.00	0.00	*206.36 FL X
28	1		*Trunk Lid Weatherstrip <i>11</i>	10.00	0.00	*318.89 FL X
29	1		*Trunk Lid Logo <i>su</i>	10.00	0.00	*196.85 FL X
30	1		*Trunk Lid E300 Emblem <i>11 106</i>	10.00	0.00	*206.36 FL ✓
31	1		*Trunk Lid Lamp LH <i>11</i>	10.00	0.00	*804.10 FL X
32	1		*Trunk Lid Lamp RH <i>11</i>	10.00	0.00	*804.10 FL X

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

13,927.99

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
			- List Item Discount on L Items (\$\$)			1,392.80
			<b>Total Parts (\$\$)</b>			<b>12,535.19</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To Panel Beat On Necessary Accident Parts	New	600 1,800.00
2	To Sand Down, Putty & Spray Painting On Necessary Accident Damaged Parts	New	800 1,700.00
3	To Diagnose and Calibrate Parktronic	New	150 350.00
4	To Diagnose and Reset Convertible Soft Cover Roof	New	11 X 350.00
5	To Check Wiring	New	20 50.00
Gross Labour Cost (S\$)			4,250.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

P-8548-41  
 102  


---

 7693.50  
 1570  


---

 9263.50  
 212  


---

 7410.