

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009864/KPA3Q2**Date:** 10/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070075761
Claimant Vehicle No :	GBD9771D	Insured Vehicle No :	GBJ5841E
Date of Loss:	29/09/2022	Nature of Claim:	TP
		Claim No:	6354952961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD9771D		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD	Engine No:	ZD30001137N
	EURO 5 (A)		
Reg. Date:	13/08/2015 (Man. Year: 2015)	Chassis No:	JN1SC2F24Z0857337
Colour:	Gold	Odometer:	174496 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,738.53	7,610.85	127.68	1.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,610.00	370.00	12.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,718.53	10,220.85	497.68	4.64
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	10,718.53	8,150.00	2,568.53	23.96
+ GST 7.00/7.00% (S\$)	750.30	570.50	179.80	23.96
Nett Amount (S\$)	11,468.83	8,720.50	2,748.33	23.96
+ Loss of Use (9.0 x S\$70.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,352.50		

INSPECTION

Date of Assignment:	10/10/2022	
Date Inspected:	10/10/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,605.60 FN	*1,605.60 FN
2	1		*LH TAILLAMP	Cracked	293.30 FN	*293.30 FN
3	1		*FRONT PANEL	Bent	1,738.90 FN	*1,738.90 FN
4	1		*FRONT PANEL EMBLEM (CABSTAR)	Necessary	62.60 FN	*62.60 FN
5	1		*FRONT GRILLE	Cracked	508.10 FN	*508.10 FN
6	1		*FRONT BUMPER	Buckled	1,053.50 FN	*1,053.50 FN
7	1		*LH HEADLAMP	Mtg Cracked	570.40 FN	*570.40 FN
8	1		*LH HEADLAMP LOWER GARNISH	Serviceable	89.40 FN	*- FN
9	1		*SET FRONT WINDSCREEN GLASS MOULDING	Necessary	435.10 FN	*435.10 FN
10	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	77.22 FS	*30.00 FS
11	1		*FRONT LH BUMPER STAY	Bent	143.00 FN	*143.00 FN
12	4		*FRONT GRILLE CLIPS	Necessary	60.00 FS	*60.00 FS
13	1		*AIRCON EVAPORATOR	Cracked	1,483.40 FS	*1,483.40 FS
14	1		*STICKER - 70KM/H	Necessary	10.00 FS	*10.00 FS
15	1		*FRONT NUMBER PLATE	Bent	18.00 FS	*18.00 FS
16	1		*SET REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
17	1		*FRONT WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
					Sub Total (\$\$)	8,388.52 8,251.90
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	649.99 641.05
					Total Parts (\$\$)	7,738.53 7,610.85

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX DASHBOARD, METER ASSY AND CHECK WIRING	New	280.00	250.00
3	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
4	PUTTY & RESPRAY ON FRT PANEL, FRT WIPER PANEL, FRT GRILLE	New	700.00	600.00
5	REMOVE & REFIX TAILGATE, TAILLAMP, KNOCK & REPAIR REAR END LOWER MEMBER & REALIGN THE SAME	New	500.00	400.00
6	PUTTY & RESPRAY ON TAILGATE & REAR END LOWER MEMBER	New	400.00	360.00
7	TO REWRITE ADVERTISEMENT	New	150.00	150.00
8	RUSTPROOFING	New	30.00	30.00
9	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, TO CUT, WELD & RENEW FRT PANEL, KNOCK & REPAIR FRT INNER PANEL & REALIGN THE SAME	New	700.00	600.00
Gross Labour Cost (S\$)			2,980.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >