



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE PRISON SERVICE LOGISTICS BRANCH		Ref: CS/SPS22009869/Uqy3e2 Date: 18/10/2022 Code: SPS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 1456G	Veh. Inspected	SMV 7045E
Policy No.	6000101314	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	AGNES WONG	Assign Date	05/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFST22P600040113	Colour	WHITE
Odometer	11324 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	AUSTONE	7 mm
L/H Front Tyre	195 R15	AUSTONE	7 mm
R/H Rear Tyre	195 R15	AUSTONE	7 mm
L/H Rear Tyre	195 R15	AUSTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/09/2022	Inspection Date	05/10/2022
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	