

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22009872/EQY3Q2**Date:** 10/11/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SMH6655A **Insured Vehicle No :** GBL918R

Date of Loss: 04/10/2022 Nature of Claim: TP Claim No: DMCV2200005H.02/GK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH6655A**

Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030222049

Reg. Date: 08/01/2015 (Man. Year: 2014) Chassis No: WDD2050402R010104

Colour: Grey Odometer: 99277 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,363.27	6,183.47	2,179.80	26.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,140.00	4,020.00	2,120.00	34.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,503.27</b>	<b>10,203.47</b>	<b>4,299.80</b>	<b>29.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,015.23</b>	<b>714.24</b>	<b>300.99</b>	<b>29.65</b>
<b>Nett Amount (S\$)</b>	<b>15,518.50</b>	<b>10,917.71</b>	<b>4,600.79</b>	<b>29.65</b>

INSPECTION

Date of Assignment: 06/10/2022

Date Inspected: 25/10/2022 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)  
188 Pandan Loop  
Singapore 128378

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Nov 2022)

**Parts:** 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMH6655A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,674.18 FS	*1,674.18 FS
2	1		*RH/FRONT BUMPER LOWER GRILLE	Not Necessary	89.47 FS	*- FS
3	1		*RH /FRONT BUMPER TOP BOTTOM MOULDING	Not Necessary	62.67 FS	*- FS
4	1		*RH /FRONT BUMPER BOTTOM MOLDING	Not Necessary	85.57 FS	*- FS
5	1		*RH /FRONT BUMPER MOUNTING RAIL	Not Necessary	15.52 FS	*- FS
6	1		*RH/ BASIC MOUNTING FOR BUMPER	Not Necessary	99.71 FS	*- FS
7	1		*FRONT DISTANCE SENSOR	Not Necessary	195.43 FS	*- FS
8	1		*RH/ FRONT BUMPER	Dented	977.57 FS	*977.57 FS
9	1		*RH/ FRONT WHEEL HOUSE FRT COVERING	Not Necessary	134.11 FS	*- FS
10	1		*RH/ HEADLAMP UNIT	Cut	3,443.48 FS	*3,443.48 FS
11	1		*FRONT STIFFENING	Not Necessary	851.45 FS	*- FS
12	1		*RH/ HEADLAMP UNIT CONTROL UNIT	Not Necessary	645.87 FS	*- FS
13	1		*RH /FRONT CROSS MEMBER BRACKET	Broken	88.24 FS	*88.24 FS
					<b>Total Parts (S\$)</b>	<b>8,363.27 6,183.47</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISHER	New	3,840.00	1,920.00
2	RESPRAY FRONT BUMPER & RH/FRONT FENDER	New	1,800.00	1,600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	TO REMOVE ,REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>6,140.00</b>	<b>4,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >