



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SBS 3154X

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	O/S CORNER BUMPER COMP MOULD CL 1FRT (CONSISTENT)	CRACKED	230.00
1	FRT OS CORNER DEFLECTOR COMP MOULD CL1 (CONSISTENT)	CRACKED	65.00
			295.00
<u>SPECIAL NETT ITEMS</u>			
1	TOUCH UP STICKER (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-
			-
<u>LABOUR</u>			
	CONTRACTOR'S REPAIR CHARGES - SOON BEE.		540.00
	WORKSHOP LABOUR.		188.00
	SPRAY PAINTING & SIKAFLEX x 255.		50.00
	VINYL. (NPA)	NOT NECESSARY	-
	TOWING. (NPA)	NOT NECESSARY	-
			778.00
GRAND TOTAL			1,073.00

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)	1,073.00
---	-----------------

Report Ref No. CS/ASM22009875/Rcy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.