

DATE: 03.10.2022
DAY : Mon

Workshop Accident Repair Estimate
FOR WORKSHOP ONLY

ACCIDENT DATE 02.02.2022 BUS REGISTRATION NUMBER SBS3154X
ACCIDENT TIME 00:17AM BUS TYPE (DD OR SD) DD
THIRD PARTY CLAIM AGAINST Accident Reference & Bus No AR-2022-2739

S/No		SECTION A :	PARTS & MATERIAL COST	
		Part or Item Description	Quantity	Total Cost
1		O/S CORNER BUMPER COMP MOULD CL 1FRT <i>cm ✓</i>	1	\$ 230.00
2		FRT OS CORNER DEFLECTOR COMP MOULD CL1 <i>cm ✓</i>	1	\$ 65.00
3				
4				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
TOTAL PARTS & MATERIAL COST			\$	295.00

S/No	SECTION B: ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)			
1	contractor's repair charges -soon Bee		Quotation	\$540
2	Workshop Labour			\$188.00
3	Spray Painting & Sikaflex x 255			\$50
4	Vinyl		NA	
5	Touch up sticker		Sticker & AVD	
6	Towing		CRS Towing	
			TOTAL LABOUR COST	\$778

SECTION C :		SUMMARY	
		TOTAL DOWNTIME-1 dar	
		TOTAL REPAIR COSTS	\$ 1,073.00

Name of Surveyor: Rasul - Hg 90010068

Company Name: LKK ANU

DATE Surveyor : 03/10/22 @ 1350

Resy before paint
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: