

ASS. REC. BY:

REF:

C12 / 220098781kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

1.51

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMS 5846P

Yr Regn:

031 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avante

c.c

1591

Colour

M. white

A/C:

Insured / Std / NI / NA

Sp. Reading

186952

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM1H0841CMLU 034261

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Interlac

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/10/22

D.O.A.

4/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm & N/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 CIA not ready

17/10/11 Rm @ 1950h Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 03/10/2022

Vehicle No: SMS5846P

Model: HYUNDAI AVANTE 1.6 GLS

Chassis: KMHD841CMLU034261 - 2019

Reg. Year: 2020

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GX6158E

Date of Accident: 01/10/2022

Estimator: KIT

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH <i>1832</i>	1		<i>B</i> \$1,993.70
2	FRONT DOOR SIDE MIRROR WITH COVER RH <i>131-20</i>	1		<i>W</i> \$281.50
3	FRONT DOOR WEATHERSTRIP RH	1		<i>SW</i> \$145.80
4	FRONT BUMPER	1		<i>R</i> \$987.60
5	FRONT FENDER RH	1		REPAIR
6	FRONT SPORT RIM RH	1		REPAIR
SUB TOTAL				\$3,408.60
LESS 20%				\$681.72
PARTS TOTAL				\$2,726.88

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR BLACK TAPE STICKER RH	1		<i>Na</i> \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.

\$500.00 *300*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.

\$700.00 *460*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 *300*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 *200*

LABOUR TOTAL \$1,380.00 *810.00*

TOTAL \$4,156.88

KIT

Parts - 1820.16
S/N - 50.00
Labour - 810.00
2680.16
-20% 536.03
2144.13
Road Up
Total - \$2100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

818 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1011 | Fax: (+65) 6481 1011

OW