

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS/AIS22009882/GNY3Q2**Date:** 29/03/2023**REFERENCE**

Insured/Claimant:	SEOW CHI HOU NELSON	Policy No:	SP2002389349
Date of Loss:	28/09/2022	Nature of Claim:	OD
		Claim No:	202222007090

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SBA71R</b>	Engine No:	G4FGHU687100
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU527392
Reg. Date:	15/08/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,679.50	1,556.50	2,123.00	57.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	580.00	590.00	50.43
Paintwork Labour	1,520.00	1,400.00	120.00	7.89
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,369.50</b>	<b>3,536.50</b>	<b>2,833.00</b>	<b>44.48</b>
<b>- Excess (\$\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>(\$\$)</b>	4,369.50	1,536.50	2,833.00	64.84
<b>+ GST 7.00/8.00% (\$\$)</b>	305.87	122.92	182.95	59.81
<b>Nett Amount (\$\$)</b>	<b>4,675.37</b>	<b>1,659.42</b>	<b>3,015.95</b>	<b>64.51</b>

**INSPECTION**

Date of Assignment:	06/10/2022 Present Location:	Kan Fook Sing Motor Workshop (Defu)
		Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	06/10/2022 Inspected At:	Blk 8 Defu South Street 1, Defu Industrial City #04-29
		Singapore 533758
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBA71R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	400.00 F	*400.00 F
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Necessary	18.00 F	*15.00 F
3	1		*FRONT SUPPORT PANEL	Not Necessary	310.00 F	*- F
4	1		*FRONT GRILLE	Not Necessary	450.00 F	*- F
5	1		*FRONT BUMPER	Deformed	350.00 F	*300.00 F
6	1		*FRONT BUMPER SIDE RETAINER LH	Broken	22.00 F	*15.00 F
7	1		*FRONT BUMPER TOP BRACKET LH	Not Necessary	40.00 F	*- F
8	10		*FRONT BUMPER CLIP	Not Necessary	25.00 F	*- F
9	1		*FRONT FENDER LH	Repair	290.00 F	*- F
10	1		*FRONT FENDER SHIELD LH	Deformed	45.00 F	*45.00 F
11	10		*FRONT FENDER SHIELD CLIP	Not Necessary	25.00 F	*- F
12	1		*FRONT DOOR LH	Repair	680.00 F	*- F
13	1		*FRONT DOOR FAME STICKER 1	Not Necessary	16.00 F	*- F
14	1		*FRONT DOOR FAME STICKER 2	Not Necessary	16.00 F	*- F
15	1		*FRONT DOOR OUTER HANDLE LH	Cut	88.00 F	*85.00 F
16	1		*FRONT SIDE MIRROR LH	Distorted	275.00 F	*295.00 F
Supplementary #1						
17	1		*FRONT SIDE MIRROR RH	Cut	295.00 F	*260.00 F
						F=Franchise part.
					Sub Total (\$\$)	3,345.00 1,415.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	334.50 141.50
					Total Parts (\$\$)	3,679.50 1,556.50
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	SPRAYPAINTING CHARGES	New	720.00	700.00
<b><u>Labour Items</u></b>				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO CHECK ALIGNMENT	New	100.00	0.00
4	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	50.00	0.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	520.00	450.00
<b><u>Supplementary #1</u></b>				
<b><u>Paintwork Labour</u></b>				
6	SPRAYPAINTING CHAREGS (RH)	New	800.00	700.00
<b><u>Labour Items</u></b>				
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (RH)	New	450.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>2,690.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >