

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22009885/UPA3Q2**Date:** 07/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001578605
<b>Claimant Vehicle No :</b>	SLK9938K	<b>Insured Vehicle No :</b>	SNE5651X
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	202222007231

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLK9938K</b>	Engine No:	3ZRB812314
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Chassis No:	ZSU600081943
Reg. Date:	09/12/2016 (Man. Year: 2016)	Odometer:	93244 km
Colour:	Silver		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55Z R18	Rear Tyre Size:	235/55Z R18
Front Left Side:	Habilead 7 mm	Rear Left Side:	Habilead 7 mm
Front Right Side:	Habilead 7 mm	Rear Right Side:	Habilead 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,907.79	1,185.41	2,722.38	69.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	820.00	1,630.00	66.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,357.79</b>	<b>2,005.41</b>	<b>4,352.38</b>	<b>68.46</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>6,357.79</b>	<b>1,600.00</b>	<b>4,757.79</b>	<b>74.83</b>
<b>+ Car Rental (4.0 x S\$120.00/day) (\$\$)</b>		480.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,087.45</b>		

INSPECTION

Date of Assignment:	06/10/2022	
Date Inspected:	06/10/2022	Inspected At: Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Dec 2022)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK9938K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,395.30 FL	*904.50 FL
2	1		*REAR BUMPER LIP	Grazed	401.95 FL	*401.95 FL
3	1		*REAR BUMPER REFLECTOR (L/H)	Cracked	62.60 FL	*62.60 FL
4	1		*REAR BUMPER SPONGE	Torn	106.40 FL	*106.40 FL
5	8		*BUMPER CLIP	Necessary	33.60 FL	*33.60 FL
6	1		*REAR END PANEL	Repair	786.90 FL	*- FL
7	1		*CONTROL UNIT (CENTRAL DOOR LOCK)	Not Necessary	572.50 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	208.60 FL	*- FL
9	1		*BUMPER SIDE RETAINER (L/H/R)	Bent	71.50 FL	*71.50 FL
10	1		*BUMPER SIDE RETAINER (R/H/R)	Not Necessary	71.50 FL	*- FL
11	1		*EMBLEM HARRIER	Not Necessary	63.60 FL	*- FL
12	1		*REAR BOOT	Not Necessary	1,232.70 FL	*- FL
13	1		*WINDSCREEN MOULDING (REAR)	Not Necessary	89.90 FL	*- FL
14	1		*BTL REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
15	1		*SEALANT (WINDSCREEN)	Not Necessary	35.00 FS	*- FS
					<hr/>	
					Sub Total (\$\$)	5,182.05 1,580.55
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,274.26 395.14
					<hr/>	
					Total Parts (\$\$)	3,907.79 1,185.41
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEAT & REPAIR REAR DAMAGE	New	1,000.00	400.00
2	TO PUTTY AND RE-SPRAY AFFECTED PORTION	New	900.00	400.00
3	TO PROVIDE UNDER TURCOAT	New	150.00	0.00
4	TO CHECK WIRING SYSTEM ,FOCUS LIGHTINGS	New	50.00	20.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
6	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	0.00
7	TO TRANSFER REAR BOOT FITTING	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,450.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >