

ASS. REC:BY: Taufik

REF: CS/ ASM 22.009888 / Tng 3

ASSIGNMENT

WE-31 DEC 2028

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 48K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBD4452H Yr Regn: 2009, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Spark TBS c.c 135

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SYP300832

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size: F: 70/90R17

R: 80/90R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 6/10/22

Survey held at Ezat Lee

Des. of Damages: F Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum \$1900 and 3 days

(red, \$3423.5, 64%)

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 3

1) 12/05/23

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.Bal. (\$ _____)

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before spray painting
 - To display damaged part(s) during survey
 - Parts prices are subject to confirmation
 - Third party survey is on a "With-out-repairer" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be surveyed and is subject to final approval from insurance company

REG. NO. 201918537M
 EMAIL : enquiry@erzatilemotor.com
 Office : 69661751

Acknowledged by Repairer
 Signature:

ESTIMATE COST OF REPAIR

Date: 5-Oct-22

Estimate no.

1169

Plate No. FBD4452H

Model. YAMAHA SPARK 135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 450.00	?	
2	FORK T-UNDER BRACKET	\$ 280.00	?	
3	STEERING CONE	\$ 150.00	?	
4	FRONT TYRES SHAFT	\$ 100.00	K	
5	FRONT SPORT RIM	\$ 250.00	x	
6	FRONT FENDER	\$ 180.00	cut	
7	HANDLE BAR	\$ 280.00	?	
8	HANDLE BRACKET	\$ 180.00	?	
9	MIRROR SET	\$ 120.00	cut	
10	CLUTH LEVEL	\$ 80.00	cut	
11	HANDLE BALANCER	\$ 100.00	cut	
12	HEAD LAMP	\$ 180.00	?	
13	HEAD LAMP STAY	\$ 150.00	?	
14	INNER PANEL	\$ 200.00	cut	
15	BASKET	\$ 120.00	bt	
16	FRONT FAIRING COVER LEFT	\$ 200.00	cut	
17	RADIATOR COOLANT	\$ 285.00	disassemble	
18	FRONT FOOTREST RUBBER	\$ 100.00	cut	
19	FRONT FOOTREST BAR	\$ 220.00	bt	
20	FRONT SPROKET COVER	\$ 120.00	cut	
21	REAR FOOTREST LEFT	\$ 120.00	bt	
22	REAR FOOTREST BRACKET LEFT	\$ 180.00	cut	
23	GEAR PEDAL	\$ 150.00	bt	
24	FRONT FAIRING INNER COVER LEFT	\$ 120.00	dis	
25	REAR BOX	\$ 450.00	cut	
26	DAY LIGHT	\$ 250.00	?	
27	FRONT PANEL COVER	\$ 180.00	cut	
28	REAR FAIRING COVER	\$ 220.00	cut	
29	LABOUR	\$ 500.00	300	

Tanfikh 97415749 / 62563561

Wp 6/10/22 @ 240pm

L/S Resurvey after repair

Tanfikh@lkkauto.com

3 days

- To check consistency of accident

- To check part prices

Less 10% \$ 591.50

\$ 5,915.00

Sub Total : \$ 5,323.50

GST 7% \$ 372.65

Total: \$ 5,696.15

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.