



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 4452H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FORK T-UNDER BRACKET (CONSISTENT)	NOT NECESSARY	280.00	-
1	STEERING CONE (CONSISTENT)	NECESSARY	150.00	50.00
1	FRONT TYRES SHAFT (CONSISTENT)	NOT NECESSARY	100.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT FENDER (CONSISTENT)	CRACKED	180.00	105.00
1	HANDLE BAR (CONSISTENT)	BENT	280.00	95.00
1	HANDLE BRACKET (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET MIRROR (CONSISTENT)	CUT	120.00	80.00
1	CLUTH LEVEL (CONSISTENT)	CUT	80.00	40.00
1	HANDLE BALANCER (CONSISTENT)	CUT	100.00	60.00
1	HEAD LAMP (CONSISTENT)	NOT NECESSARY	180.00	-
1	HEAD LAMP STAY (CONSISTENT)	NOT NECESSARY	150.00	-
1	INNER PANEL (CONSISTENT)	CRACKED	200.00	118.00
1	BASKET (CONSISTENT)	BENT	120.00	65.00
1	FRONT FAIRING COVER LEFT (CONSISTENT)	CRACKED	200.00	180.00
1	RADIATOR COOLANT (CONSISTENT)	DENTED	285.00	200.00
1	FRONT FOOTREST RUBBER (CONSISTENT)	MISSING	100.00	50.00
1	FRONT FOOTREST BAR (CONSISTENT)	BENT	220.00	90.00
1	FRONT SPROKET COVER (CONSISTENT)	DENTED	120.00	120.00
1	REAR FOOTREST LEFT (CONSISTENT)	BENT	120.00	50.00
1	REAR FOOTREST BRACKET LEFT (CONSISTENT)	CUT	180.00	80.00
1	GEAR PEDAL (CONSISTENT)	BENT	150.00	85.00
1	FRONT FAIRING INNER COVER LEFT (CONSISTENT)	DISTORTED	120.00	120.00
1	REAR BOX (CONSISTENT)	CUT	450.00	300.00
1	DAY LIGHT (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT PANEL COVER (CONSISTENT)	CUT	180.00	120.00
1	REAR FAIRING COVER (CONSISTENT)	CRACKED	220.00	150.00
	LESS 10% DISCOUNT		-496.50	-215.80
			4,468.50	1,942.20



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET FORK (SN) (CONSISTENT) LESS 10% DISCOUNT  <u>LABOUR</u> LABOUR.	SHIFTED	450.00	120.00
			-45.00	-
			405.00	120.00
			500.00	300.00
			500.00	300.00
GRAND TOTAL			5,373.50	2,362.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00
---	--	--	--	----------

Report Ref No. CS/ASM22009888/Tny3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.