

REPAIR ESTIMATEDATE: **05.10.2022**INSURANCE: **INCOME** (LKS)MODEL: **Hyundai Ioniq**SURVEYOR: **LKK-**VEHICLE NO.: **SHC3783T**MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper / <i>re</i>	1		\$ 459.40
	Rear Bumper Reinforcement ?	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH / RH ?	2	\$ 138.10	\$ 276.20
	Rear Bumper Side Brackets LH / RH <i>X na</i>	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding / <i>re</i>	1		\$ 451.25
	Rear Bumper Lower Centre Moulding <i>X na</i>	1		\$ 155.00
	Rear Bumper Cover Clips / <i>re</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH / RH <i>X na</i>	2	\$ 41.45	\$ 82.90
	Rear Bumper Tow Cover <i>X na</i>	1		\$ 98.80
	Rear Bumper Fog Lamp	1		\$ 201.50
	Rear Smart Key Antenna ?	1		\$ 40.50
	SUB TOTAL			\$ 2,293.95
	LESS 20%			\$ 458.79
	DISCOUNTED TOTAL			\$ 1,835.16
	Reverse Sensors / <i>cut</i>	1		\$ 180.00
	Rear No. Plate With Trim Cover / <i>cut</i>	1		\$ 55.00
	S/NETT SUB			\$ 235.00
	LESS 10%			\$ 23.50
	S/NETT TOTAL			\$ 211.50
	Rear Fender Adv. Sticker RH / LH / <i>MC</i>	2	\$ 100.00	\$ 200.00
	Rear Bumper Mat / <i>MC</i>	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 2,296.66
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Towing Fee			-
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 3,116.66

300 350
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

the Repairer of the following after the
to resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification allowed
- Supplier's responsibility is surveyed and is subject to the insurance Company

Acknowledge _____

Signature: _____

Date: _____

2 Dams. 5/10/22
4/5
Caroline 4pm