



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6445K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RADIATOR GRILLE	CRACKED	1,409.10	1,409.10
1	FRONT BUMPER COVER	DEFORMED	481.10	481.10
1	FRONT BUMPER UPPER MOULDING	CUT	368.50	368.50
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	318.80	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	DAYLIGHT GRILLE LH	CUT	93.45	93.45
1	HEADLAMP LH	CUT	2,110.30	2,110.30
	LESS 20% DISCOUNT		-960.65	-896.89
			3,842.60	3,587.56
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTINGS .		40.00	30.00
			740.00	630.00
GRAND TOTAL			4,582.60	4,217.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,350.00

Report Ref No. NS/INC22009892/Tqcq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.