

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009895/EVY3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00013892200

Claimant Vehicle No : SMQ7869X **Insured Vehicle No :** SLM885C

Date of Loss: 04/10/2022 Nature of Claim: TP Claim No: SNM22D207137/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ7869X**

Make & Model: SUBARU IMPREZA, 2.0 5D I-S EYESIGHT AWD CVT (A) Engine No: FB20CE38671

Reg. Date: 30/11/2019 (Man. Year: 2018) Chassis No: JF1GK7KL5KG011863

Colour: Red Odometer: 39760 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,000.80	4,047.76	953.04	19.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	4,260.00	810.00	15.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,070.80	8,307.76	1,763.04	17.51
+ GST 7.00/7.00% (S\$)	704.96	581.54	123.42	17.51
Nett Amount (S\$)	10,775.76	8,889.30	1,886.46	17.51

INSPECTION

Date of Assignment: 06/10/2022

Date Inspected: 06/10/2022 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

NOTE:VEHICLE CONVERT TO OD CLAIM.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$775.36 NETT)

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2022)**Parts:** 144 SUBARU IMPREZA 2.0 5D I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMQ7869X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RAD PNL COMPL RPR	*Check	387.20 FN	*- FN
2	1		*FENDER F LH	Dented	222.00 FN	*222.00 FN
3	1		*HOOD COMPL F	Dented	1,102.60 FN	*1,102.60 FN
4	1		*COVER FENDER UPR LH	*Check	18.50 FN	*- FN
5	1		*BUMPER FACE F STDFHI	Broken	447.70 FN	*447.70 FN
6	1		*ENR ABSORB PL UPR	*Check	67.70 FN	*- FN
7	1		*ENR ABSORB FOAM STD	*Check	61.80 FN	*- FN
8	1		*ENR ABSORB LWR F STD	Broken	39.00 FN	*39.00 FN
9	1		*BRKT CORNER F FHILH	Broken	37.00 FN	*37.00 FN
10	1		*BRKT SD F RH	*Check	22.20 FN	*- FN
11	1		*BRKT SD F LH	Broken	22.20 FN	*22.20 FN
12	1		*BRKT CTR LWR F FHI	*Check	37.00 FN	*- FN
13	1		*BEAM COMPL F EU	Bent	355.60 FN	*355.60 FN
14	1		*PLATE UPR F	*Check	29.60 FN	*- FN
15	1		*COVER FOG F STD LH	Missing	66.60 FN	*66.60 FN
16	1		*COVER INT F STD FHI	*Check	55.50 FN	*- FN
17	1		*COVER HOOK F STD	Not Necessary	11.10 FN	*- FN
18	1		*COVER UPR F FHI	*Check	23.30 FN	*- FN
19	1		*SEALING BUMPER F FHI	*Check	22.20 FN	*- FN
20	1		*MUD GUARD ASSY F LH	Not Necessary	111.00 FN	*- FN
21	1		*LAMP ASSY HEAD (LH)	Broken	2,520.00 FN	*2,520.00 FN
22	1		*GRILLE F BASE FHI	Cut	111.00 FN	*111.00 FN
23	1		*MOLDING WG PLT FHI (LH)	Cut	111.00 FN	*111.00 FN
24	1		*MOLDING WG PLT FHI (RH)	*Check	111.00 FN	*- FN
25	1		*MOLDING RNG PAINTFHI	*Check	133.20 FN	*- FN
26	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,226.00	5,054.70
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	1,225.20	1,006.94
Total Parts (\$\$)	5,000.80	4,047.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT HOOD ,FRT BUMPER ,FRT LH FENDER ,SUPPORT PANEL	New	2,480.00	1,800.00
2	RESRPAY FRONT HOOD ,FRT BUMPER ,FRT LH FENDER ,SUPPORT PANEL	New	2,160.00	2,080.00
3	TO CONDUCT WATER SEEPAGE TEST	New	100.00	50.00
4	TO CONDUCT (FRONT) LIGHTING TEST	New	50.00	50.00
5	FAULT DIAGNOSTIC (RESET)	New	280.00	280.00
			Gross Labour Cost (\$\$)	4,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >