11/7/22, 9:49 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009896/EVY3Q2

07/11/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00134352101

TP

Claimant Vehicle

SMG6150U

Insured Vehicle No:

YP4916B

Date of Loss:

No:

03/10/2022

Nature of

Claim:

Claim

SNM22D207046/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMG6150U Reg No:

PEUGEOT 308, 1.2 SW ALLURE PURETECH 2WD Make & Model:

Engine No: 10XTA40954675

Odometer:

S/R. (A) Reg. Date:

27/12/2018 (Man. Year: 2018)

Chassis No: VF3LRHNYWJS091806

101002 km

Colour: White

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm Front Right Side: Rear Right Side: Michelin 4 mm Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,755.00	1,014.50	1,740.50	63.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,650.00	750.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,155.00	2,664.50	2,490.50	48.31
+ GST 7.00/7.00% (S\$)	360.85	186.52	174.33	48.31
Nett Amount (S\$)	5,515.85	2,851.02	2,664.83	48.31

INSPECTION

06/10/2022 Date of Assignment:

Vantage Automotive Limited (Alexandra)

305 Alexandra Road #02-01, Vantage Automotive Date Inspected: 12/10/2022 Inspected At:

Centre

Singapore 159942

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11/7/22, 9:49 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Nov 2022)

Parts: N/A PEUGEOT 308 1.2 SW ALLURE PURETECH 2WD S/R. (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SMG6150U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*REAR BUMPER -W/OUT SENSOR	Dented	828.00 FS	*828.00 FS
3	1		*RR BUMPER SKIRT	Not Necessary	253.80 FS	*- FS
4	1		*RR BUMPER CENTRAL BRACKET	Not Necessary	106.20 FS	*-FS
5	1		*RR BUMPER BRACKET SUPERIEUR	Not Necessary	175.50 FS	*- FS
6	1		*RR BPR REINFORCEMENT	Not Necessary	376.20 FS	*-FS
7	4		*SENSOR -OBSTACLE DETECTION FRT /REAR	Not Necessary	748.80 FS	*-FS
8	1		*BUMPER SUPPORT FOR SENSORS	Necessary	130.50 FS	*130.50 FS
9	1		*RR BUMPER REFLECTOR RH	Broken	36.00 FS	*36.00 FS
F=Fra	nchise	part. S=SpcN	Nett.	-		
				Total Parts (S\$)	2,755.00	1,014.50
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REPLACE REAR BUMPER	New	600.00	600.00
2	SPRAY PAINT REAR BUMPER	New	600.00	600.00
3	SPRAY PAINT REAR TAILGATE	New	600.00	0.00
4	TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION	New	600.00	450.00
	Gross Labo	our Cost (S\$)	2,400.00	1,650.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >