



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 1119E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LHS 1ST LUGGAGE COMPARTMENT PANEL	TO REPAIR SEE LABOUR	1,050.00	-
1	LHS 2ND LUGGAGE COMPARTMENT PANEL	TO REPAIR SEE LABOUR	1,050.00	-
1	REAR RHS TYRE COMPARTMENT PANEL	TO REPAIR SEE LABOUR	950.00	-
2	LUGGAGE COMPARTMENT LOCK	SCRATCHED (1PC ONLY)	560.00	280.00
	LESS 10% DISCOUNT		-	-28.00
			3,610.00	252.00
	<u>LABOUR</u>			
	TO JACK / KNOCK / STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING & CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME. INCLUSIVE OF THE REPAIR OF LHS 1ST LUGGAGE COMPARTMENT PANEL, LHS 2ND LUGGAGE COMPARTMENT PANEL AND REAR RHS TYRE COMPARTMENT PANEL.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING ON LHS 1ST & 2ND LUGGAGE COMPARTMENT PANEL, REAR RHS TYRE COMPARTMENT PANEL AND AFFECTED ACCIDENT PARTS.		1,500.00	800.00
			2,700.00	1,400.00
GRAND TOTAL			6,310.00	1,652.00
RECOMMENDED COST OF REPAIRS				1,652.00

Report Ref No. CS/UOI22009901/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.