

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009906/EPA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No: SP0001081947

Claimant Vehicle No : SLK554T**Insured Vehicle No :** CB6490H

Date of Loss: 05/10/2022

Nature of Claim: TP

Claim No: TBA

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLK554T**

Make & Model: TOYOTA WISH, 1.8 X CVT (A)

Engine No: 2ZR1737045

Reg. Date: 03/01/2017 (Man. Year: 2016)

Chassis No: ZGE206030485

Colour: Black

Odometer: 163712 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,853.20	5,555.20	1,298.00	18.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	2,480.00	620.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,953.20	8,035.20	1,918.00	19.27
Approved Total (Overridden) (S\$)		6,450.00		
(S\$)	9,953.20	6,450.00	3,503.20	35.20
+ GST 7.00/8.00% (S\$)	696.72	516.00	180.72	25.94
Nett Amount (S\$)	10,649.92	6,966.00	3,683.92	34.59
+ Car Rental (12.0 x S\$110.00/day) (S\$)		1,320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,288.00		

INSPECTION

Date of Assignment: 06/10/2022 Present Location:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)

Date Inspected: 07/10/2022 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK554T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Dented	250.00 F	*250.00 F
2	10		*REAR BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
3	2		*REAR BUMPER RETAINER (WCP)	Broken	80.00 F	*80.00 F
4	1		*REAR BUMPER REFLECTOR RH (WCP)	Cut	40.00 F	*40.00 F
5	1		*REAR PARKING SENSOR	Shorted	180.00 FS	*180.00 FS
6	1		*REAR TAILLAMP RH (WCP)	Broken	130.00 F	*130.00 F
7	1		*REAR TAILLAMP RETAINER (WCP)	Missing	40.00 F	*40.00 F
8	1		*REAR BOOTLID (WCP)	Dented	520.00 F	*520.00 F
9	2		*REAR BOOT HINGE (WCP)	Bent	80.00 F	*80.00 F
10	1		*REAR BOOT LOCK (WCP)	Jammed	150.00 F	*150.00 F
11	1		*REAR BOOT TRIMBOARD (WCP)	Crushed	280.00 F	*280.00 F
12	1		*REAR BOOT EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
13	1		*REAR BOOT VALVEMATIC LOGO (WCP)	Necessary	40.00 F	*40.00 F
14	1		*REAR BOOT CHROME (WCP)	Broken	130.00 F	*130.00 F
15	2		*REAR BOOT LAMP (WCP)	Broken	260.00 F	*260.00 F
16	1		*REAR BOOT RUBBER (WCP)	Crushed	130.00 F	*130.00 F
17	1		*REAR END PANEL (WCP)	Dented	190.00 F	*190.00 F
18	1		*REAR END PANEL TOP GARNISH (WCP)	Crushed	120.00 F	*120.00 F
19	1		*REAR WINDSCREEN (WCP)	Broken	450.00 F	*450.00 F
20	1		*REAR WINDSCREEN INNER TRIM RH (WCP)	Cut	240.00 F	*240.00 F
21	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN MOULDING (WCP)	Necessary	150.00 F	*150.00 F
23	2		*REAR WINDSCREEN SIDE MOULDING (WCP)	Not Necessary	100.00 F	*- F
24	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
25	1		*REAR FENDER RH (WCP)	Dented	450.00 F	*450.00 F
26	1		*REAR FENDER GLASS WITH MOULDING (WCP)	Necessary	450.00 F	*450.00 F
27	1		*REAR FENDER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
28	1		*REAR FENDER INNER TRIM (WCP)	Crushed	450.00 F	*450.00 F
29	1		*REAR SPARETYRE PANEL (WCP)	Repair	350.00 F	*- F
Report was unsubmitted during this print-out.						

5/18/23, 2:49 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*REAR SPARETYRE BOARD (WCP)	Not Necessary	450.00 F	*- F
31	1		*REAR WIPER ARM (WCP)	Cut	70.00 F	*70.00 F
32	1		*REAR WIPER BLADE (WCP)	Cut	22.00 F	*22.00 F
33	1		*REAR WIPER MOTOR (WCP)	Not Necessary	280.00 F	*- F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					6,257.00	5,077.00
+ Margin on L,N Items 10.00/10.00% (S\$)					596.20	478.20
Total Parts (S\$)					6,853.20	5,555.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX SEATS	New	150.00	80.00
2	TO KNOCK, STRAIGHTHEN CHASSIS,WELD,REMOVE & FIX ON ABOVE PARTS	New	1,200.00	1,200.00
3	TO REMOVE & FIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX TRIM	New	200.00	80.00
5	TO PUTTY & SPRAY PAINTING ON CHASSIS,RR FENDER LH & AFFECTED AREAS	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			3,100.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >