

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22009908/RQY3E2**Date:** 18/04/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SHB1336U**Insured Vehicle No :** YQ6020S

Date of Loss: 04/10/2022

Nature of Claim: TP

Claim No: CDMCG22002080

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SHB1336U**

Make &amp; Model: TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)

Engine No: 2ZRS103807

Reg. Date: 28/11/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU403574338

Colour: Maroon

Odometer: 482165 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Giti 6 mm

Rear Left Side:

Giti 6 mm

Front Right Side: Giti 6 mm

Rear Right Side:

Giti 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,008.30	565.26	10,443.04	94.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,614.00	400.00	1,214.00	75.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,622.30</b>	<b>965.26</b>	<b>11,657.04</b>	<b>92.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>850.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,622.30</b>	<b>850.00</b>	<b>11,772.30</b>	<b>93.27</b>

**INSPECTION**

Date of Assignment: 06/10/2022

Date Inspected: 06/10/2022 Inspected At:

Strides Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2022)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB1336U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FR BUMPER (DISC 25%)	Torn	560.30 F	*420.23 F
2	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	98.70 F	*74.03 F
3	10		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%)	Necessary	48.00 F	*36.00 F
4	1		*NUMBER PLATE (SN)	Scratched	35.00 F	*35.00 F
5	1		*SUPPORT, FR BUMPER RH	Not Necessary	86.20 F	*- F
6	1		*COVER, FR BUMPER RH	Not Necessary	31.80 F	*- F
7	1		*BRACKET, FR BUMPER	Not Necessary	111.80 F	*- F
8	1		*REINFORCEMENT FRONT UPPER	Not Necessary	773.90 F	*- F
9	1		*ABSORBER, FR BUMPER	Not Necessary	85.90 F	*- F
10	1		*EXTENSION SUB-ASSY, LH	Not Necessary	129.90 F	*- F
11	1		*EXTENSION SUB-ASSY, RH	Not Necessary	129.90 F	*- F
12	1		*SEAL, HOOD TO FR END	Not Necessary	55.80 F	*- F
13	1		*GRILLE, RADIATOR	Not Necessary	183.90 F	*- F
14	1		*GRILLE SUB-ASSY	Not Necessary	374.40 F	*- F
15	1		*RETAINER, FR BUMPER, LH & RH	Not Necessary	9.50 F	*- F
16	1		*LAMP ASSY, FOG, RH	Not Necessary	1,029.90 F	*- F
17	1		*UNIT, HEADLAMP, RH	Not Necessary	2,852.40 F	*- F
18	1		*UNIT, HEADLAMP, LH	Not Necessary	2,852.40 F	*- F
19	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Not Necessary	1,039.90 F	*- F
20	1		*SUPPORT S/A UPPER	Not Necessary	408.50 F	*- F
21	1		*SUPPORT, RADIATOR UPPER RH	Not Necessary	85.20 F	*- F
22	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**      **11,008.30**      **565.26**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,614.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >