

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22009909/AQCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant:	WONG EE KAY GEOFFREY	Policy No:	7220082881	
Date of Loss:	06/09/2022	Nature of Claim:	OD	Claim No: 3712623290SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNH25X</b>		Engine No:	DCB531578
Make & Model:	AUDI Q7, 3.0 TFSI QU (333 BHP) (A)		Chassis No:	WAUZZZ4MXND022969
Reg. Date:	28/07/2022 (Man. Year: 2022)		Odometer:	4812 km
Colour:	Black			
Engine Capacity:	2995 cc			
Market Value/New Car Price:	S\$320,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	285/45 R20	Rear Tyre Size:	285/45 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,710.00	1,174.40	14,535.60	92.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,452.00	2,992.00	9,460.00	75.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,162.00</b>	<b>4,166.40</b>	<b>23,995.60</b>	<b>85.21</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	27,762.00	3,766.40	23,995.60	86.43
<b>+ GST 8.00/8.00% (S\$)</b>	2,220.96	301.31	1,919.65	86.43
<b>Nett Amount (S\$)</b>	<b>29,982.96</b>	<b>4,067.71</b>	<b>25,915.25</b>	<b>86.43</b>

**INSPECTION**

Date of Assignment:	07/10/2022		
Date Inspected:	06/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Repair	5,466.00 FS	*- FS
2	1		*FRONT OUTER DOOR SEAL	Not Necessary	282.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH - RH	Not Necessary	137.00 FS	*- FS
7	1		*FRONT DOOR COVER - RH	Repair	963.00 FS	*- FS
8	1		*REAR DOOR - RH	Repair	5,708.00 FS	*- FS
9	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
10	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
11	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
12	1		*REAR DOOR CATCH - RH	Not Necessary	137.00 FS	*- FS
13	1		*REAR OUTER DOOR SEAL - RH	Not Necessary	213.00 FS	*- FS
14	1		*REAR WEATHER STRIP	Not Necessary	282.00 FS	*- FS
15	1		*REAR DOOR COVER - RH	Cut	883.00 FS	*706.00 FS
16	1		*REAR DOOR WHEEL COVER - RH	Cut	201.00 FS	*160.40 FS
17	1		*REAR WHEEL COVER - LH / RH	O/S Cut	770.00 FS	*308.00 FS
18	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	15,710.00 1,174.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	900.00	300.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	600.00
4	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, 2 DOOR COVERS, DOOR HANDLES, RHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS	New	7,000.00	1,900.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>12,452.00</b>	<b>2,992.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >