

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22009911/AQY3E2**Date:** 13/04/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22001399
Claimant Vehicle No :	SKF3337Y	Insured Vehicle No :	GBG5446D
Date of Loss:	05/10/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002083

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF3337Y	Engine No:	F2741872B48B20A
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBA8G32090A062582
Reg. Date:	31/08/2018 (Man. Year: 2018)	Odometer:	56457 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,151.75	6,090.35	12,061.40	66.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	860.00	1,930.00	69.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,941.75	6,950.35	13,991.40	66.81
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	20,941.75	5,500.00	15,441.75	73.74

INSPECTION

Date of Assignment:	07/10/2022	
Date Inspected:	10/10/2022	Inspected At: TSL Auto Garage Blk 1 Kaki Bukit Avenue 6 #01-08 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2023)
Parts:	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF3337Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SPORT BUMPER WITH SPOILER COMPLETE ASSY	Deformed	3,467.50 FS	*2,000.00 FS
2	2		*FRONT BUMPER RETAINER	Not Necessary	225.00 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Not Necessary	128.00 FL	*- FL
4	1		*FRONT BUMPER LEFT INNER UPPER GARNISH	Not Necessary	165.00 FL	*- FL
5	1		*FRONT BUMPER LEFT INNER LOWER GARNISH	Not Necessary	165.00 FL	*- FL
6	1		*SET FRONT SUPPORT PANEL INNER GARNISH	Not Necessary	160.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	625.00 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Cracked	163.00 FL	*163.00 FL
9	1		*FRONT BUMPER TOW COVER	Not Necessary	88.00 FL	*- FL
10	1		*FRONT BUMPER CENTRE LOGO	Necessary	128.00 FL	*75.00 FL
11	1		*FRONT LEFT LED HEADLAMP	Cracked	3,250.00 FL	*3,250.00 FL
12	1		*FRONT LEFT LED HEADLAMP MODULE	Not Necessary	1,250.00 FL	*- FL
13	1		*FRONT LEFT LED HEADLAMP BRACKET	Not Necessary	125.00 FL	*- FL
14	1		*FRONT BONNET ASSY	Not Necessary	2,350.00 FL	*- FL
15	1		*FRONT FOG LAMP	Cracked	290.00 FL	*290.00 FL
16	1		*FRONT FOG LAMP GARNISH	Cracked	85.00 FL	*85.00 FL
17	2		*FRONT BONNET HINGES	Not Necessary	160.00 FL	*- FL
18	1		*FRONT BONNET INSULATOR	Not Necessary	280.00 FL	*- FL
19	2		*FRONT BONNET LOCK CATCH	Not Necessary	108.00 FL	*- FL
20	1		*SET FRONT BONNET LOCK MECHANISM	Not Necessary	385.00 FL	*- FL
21	1		*FRONT KIDNEY GRILLE ASSY	N/S Cracked	650.00 FL	*215.00 FL
22	1		*FRONT KIDNEY GRILLE INNER AIR VENT ASSY	Not Necessary	350.00 FL	*- FL
23	1		*FRONT KIDNEY GRILLE INNER GARNISH ASSY	Not Necessary	205.00 FL	*- FL
24	1		*FRONT LEFT AIR DUCT VENT	Deformed	175.00 FL	*175.00 FL
25	1		*FRONT LEFT FENDER	Repair	1,395.00 FL	*- FL
26	2		*FRONT LEFT FENDER INNER COWLING	Not Necessary	325.00 FL	*- FL
27	1		*FRONT LEFT SIDE LOWER COVER	Not Necessary	185.00 FL	*- FL
28	12		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*SET FRONT BUMPER PARKING SENSOR	Not Necessary	1,200.00 FS	*- FS
30	1		*SET FRONT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	450.00 FS	*- FS
31	1		*FRONT NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
32	1		*FRONT KIDNEY GRILLE ASSY CLIPS (6PCS)	Necessary	50.00 FS	*20.00 FS
33	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
34	8		*FRONT LEFT FENDER INNER COWLING CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,822.50 6,303.00
- List Item Discount on L Items 5.00/5.00% (\$\$) 670.75 212.65

Total Parts (\$\$) 18,151.75 6,090.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT, FRONT LEFT AFFECTED AREA AND REPLACE FRONT AND FRONT LEFT DAMAGED PARTS	New	1,200.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION	New	1,200.00	400.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	30.00
4	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	80.00	0.00
5	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	140.00	30.00
6	TOWING SERVICE	New	120.00	0.00
Gross Labour Cost (S\$)			2,790.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >