


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Thiam Heng Hwy
 of 017C
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PKD 006B Yr Regn: 05, 22
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Lexus 1S300h c.c. 2494
 Colour: M.P. white A/C: Insured / Std / Nil / NA
 Sp. Reading: 3969 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: J714BH102205088392
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD / A/Rim or _____
 Tyre Size: F: _____
 R: 235/45R18

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 8243k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 02-3 days Res.: Yes or No
 Lum Sum: 1.8.1 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 9 mm
 L/Bal. 9 mm
 D.O.A. 5/10/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	EM not ready
12/10	83336.89 Cash

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation _____
 \$ + RS. _____
 Fuel _____
 Others _____
 TOTAL _____

Kg Repair Estimate

Not Authorised
Return by paint
3 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

3336.89

Make/Model: LEXUS IS300h
Engine/Chassis No.: JTHBH1D2205088392
Date of accident:
Damaged area: Rear

Date: 10/10/2022
Claim Type: TP
VRN: SKD606B

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *[Signature]*
Date: *10/10/2022*

S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>1248-40</i>	1	\$ 1,995.00	\$ 1,995.00
2	Rear bumper lower <i>138-10</i>	1	\$ 744.00	\$ 744.00
3	Rear bumper inner sponge	1	\$ 268.00	\$ 268.00
4	Rear bumper side retainer	2	\$ 118.00	\$ 236.00
5	Rear bumper reinforcement	1	\$ 475.70	\$ 475.70
6	Rear bumper reinforcement bracket	2	\$ 109.00	\$ 218.00
7	Rear bumper sensor holder	2	\$ 26.40	\$ 52.80
Subtotal				\$ 3,989.50
List discount				10.00%
Total				\$ 3,590.55

✓
✓
✓
X
X
X
X

No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper clips	12	\$ 5.50	\$ 66.00
2	Reverse sensor (Factory Original) <i>-10%</i>	2	\$ 490.80	\$ 981.60
3	Sundries	1	\$ 80.00	\$ 80.00
Total				\$ 1,127.60

✓
✓
X

No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.75	\$ 150.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,450.00

200l
20l
250l
X

Estimate Grand Total	\$ 7,168.15
----------------------	-------------