

A&S. REC:BY: Tau Jhu

REF:

CC/41622 009918/TP 93.**ASSIGNMENT**

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$170K.

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

WP'

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Henry Vehicle: IN / OUTVeh No: SKA609J. Yr Regn: 2019 July.Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 5201 C.C. 1998Colour: Blue. A/C: Insured / Std / NI / NASp. Reading: 34869 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJA12080 B*T82719Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R18R: 1 2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 14/10/22.Survey held at Woon Mang Sht Bth

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt 2/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungai Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng@singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 13 Oct 2022

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR BMW 520D - SKA609J
ACCIDENT INVOLVING SKA609J & GBH6587T ON 06/10/2022

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper	1pc	\$ 1,600.00 <i>de</i> ✓
2	Front bumper retainer upper rh	1pc	\$ 50.00 X
3	Front bumper retainer lower rh	1pc	\$ 35.00 X
4	Front bumper fog lamp rh	1pc	\$ 480.00 X
5	Front bumper fog lamp grille rh	1pc	\$ 150.00 <i>de</i> ✓
6	Front center grille rh	1pc	\$ 360.00 X
7	Front headlamp rh	1pc	\$ 5,500.00 <i>cur</i> ✓
8	Front center grille chrome rh	1pc	\$ 185.00 X
9	Front bumper sensor @\$280ea	2pcs	\$ 560.00 X
10	Front fender rh	1pc	\$ 1,100.00 <i>Rx</i>
	Sum Carried Forward		\$ 10,020.00

Sum Carried Forward

\$ 10,020.00

Labour Charge & Misc

To remove, replace, repair & weld
rear damaged parts.

\$ 900.00 600

To R & R sensor wiring

\$ 120.00 80

To R & R light wiring.

\$ 80.00 30

To putty & spray painting

\$ 1,000.00 700

Total

\$ 11,120.00

All prices quoted are subjected to 7% GST.

Taufik 97495749
WP 14/10/22 @ 10am
4/5 Resurvey after report
taufik@lkkauto.com.
3 days

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: