

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22009919/KQY3Q2
Date: 22/12/2022**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG21013181
Claimant Vehicle No :	GBC46D	Insured Vehicle No :	GBL1250B
Date of Loss:	03/10/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002075

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC46D	Engine No:	ZD30269560K
Make & Model:	NISSAN URVAN, 3.0 LWB 5DR 4AT ABS A/B (M)	Chassis No:	JN1MG4E25Z0794615
Reg. Date:	31/12/2010 (Man. Year: 2010)	Odometer:	224401 km
Colour:	White		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,087.00	7,909.89	2,177.11	21.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	3,330.00	1,260.00	27.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,677.00	11,239.89	3,437.11	23.42
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	14,677.00	9,000.00	5,677.00	38.68

INSPECTION

Date of Assignment:	07/10/2022	
Date Inspected:	07/10/2022 Inspected At:	Rc Auto-160 Sin Ming (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 22 Dec 2022)	
Parts:	N/A	NISSAN URVAN 3.0 LWB 5DR 4AT ABS A/B (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC46D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	2,150.00 F	*2,101.00 FL
2	1		*REAR BOOTLID LOCK	Repair	120.00 F	*- FL
3	1		*REAR LAMP (R/H)	Serviceable	354.00 F	*- FL
4	1		*REAR PANEL	Bent	420.00 F	*420.00 FL
5	1		*REAR PANEL BRACKET	Distorted	190.00 F	*190.00 FL
6	1		*FRONT PANEL	Bent	790.00 F	*790.00 FL
7	1		*FRONT GRILLE	Cracked	450.00 F	*450.00 FL
8	1		*FRONT HEADLAMP	Cracked	560.00 F	*560.00 FL
9	1		*FRONT CORNER PANEL	Bent	210.00 F	*210.00 FL
10	1		*FRONT SIDE LAMP	Cracked	190.00 F	*190.00 FL
11	1		*FRONT WINDSCREEN RUBBER (FRONT)	Necessary	115.00 F	*115.00 FL
12	1		*FRONT BLOWER UNIT	Housing Cracked	1,800.00 F	*1,470.55 FL
13	1		*FRONT COOLING COIL ASSY	Cracked	908.00 F	*810.00 FL
14	1		*REAR WINDSCREEN RUBBER (REAR)	Not Necessary	130.00 F	*- FL
15	1		*FRONT BLOWER UNIT AIRCON HOSE	Serviceable	180.00 F	*- FL
16	1		*REAR BUMPER	Bent	590.00 F	*590.00 FL
17	1		*FRONT BUMPER	Bent	620.00 F	*620.00 FL
18	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*25.00 FS
19	1		*60KM/H STICKER	Necessary	10.00 FS	*10.00 FS
20	1		*6 PAX STICKER	Necessary	10.00 FS	*10.00 FS
21	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,087.00	8,761.55
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	851.66
Total Parts (S\$)	10,087.00	7,909.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	60.00	60.00
2	AIRCON TOP UP AND INSTALLTION	New	150.00	100.00
3	TO REMOVE DASHBOARD	New	200.00	200.00
4	TO REMOVE FRONT WINDSCREEN	New	150.00	120.00
5	TO REMOVE REAR BOOTLID GLASS	New	150.00	120.00
6	REAR BOOTLID BODY LETTERING	New	300.00	150.00
7	ANTI RUST	New	50.00	50.00
8	TO RESPRAY JOB	New	1,500.00	1,200.00
9	LABOUR CHARGES TO REMOVE ABOVE PARTS	New	2,000.00	1,300.00
10	TO CHECK WIRING	New	30.00	30.00
			Gross Labour Cost (S\$)	4,590.00
				3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >