



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3335G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | COVER FOR BUMPER PRIMED (SN) | BROKEN | 1,382.73 | 1,382.73 |
| 1 | COVER FOR TOWING EYE PRIM (SN) | CRUSHED | 33.66 | 33.66 |
| 1 | GUIDE PIECE LHR BUMPER BRACKET (SIDE) (SN) | NOT NECESSARY | 41.89 | - |
| 1 | GUIDE PIECE RHR BUMPER BRACKET (SIDE) (SN) | NOT NECESSARY | 41.89 | - |
| 1 | GUIDE PIECE LHR BUMPER BRACKET (OUTER) (SN) | NOT NECESSARY | 41.89 | - |
| 1 | GUIDE PIECE RHR BUMPER BRACKET (OUTER) (SN) | NOT NECESSARY | 41.89 | - |
| 1 | ATTACHMENT STRIP RR BUMPER BRACKET (CENTER) (SN) | NOT NECESSARY | 70.74 | - |
| 1 | SENSOR PRIMED (SN) | NOT NECESSARY | 190.18 | - |
| 4 | SEAL RING SATIN BLACK (SN) | NECESSARY | 5.84 | 5.84 |
| 2 | SENSOR BRACKET (SN) | NECESSARY | 27.20 | 27.20 |
| 1 | SENSOR BRACKET (SN) | NECESSARY | 14.19 | 14.19 |
| 1 | SENSOR BRACKET (SN) | NECESSARY | 13.60 | 13.60 |
| 1 | 2K-PLASTIC ADHESIVE (SN) | NECESSARY | 85.94 | 85.94 |
| 1 | BONDING AGENT FOR PLASTIC (SN) | NECESSARY | 68.85 | 68.85 |
| 1 | BUMPER (SN) | NOT NECESSARY | 732.39 | - |
| 4 | RIVET (SN) | NECESSARY | 1.76 | 1.76 |
| 1 | REAR DIFFUSOR SATIN BLACK (SN) | NOT NECESSARY | 349.21 | - |
| 1 | DECORATIVE MOULDING BRIGH REAR BUMPER LOWER CHROME MOLDING (CENTER) (SN) | NOT NECESSARY | 159.63 | - |
| 1 | DECORATIVE MOULDING BRIGH LHR BUMPER CHROME MOULDING (SN) | NOT NECESSARY | 131.29 | - |
| 1 | DECORATIVE MOULDING BRIGH RHR BUMPER CHROME MOULDING (SN) | NOT NECESSARY | 131.29 | - |
| 1 | REFLECTOR LH (SN) | NOT NECESSARY | 79.04 | - |
| 1 | REFLECTOR RH (SN) | NOT NECESSARY | 79.04 | - |
| 1 | REAR TRUNK LID (SN) | DENTED | 3,107.80 | 3,107.80 |
| 1 | GASKET BOOT LID SEAL (SN) | NOT NECESSARY | 289.35 | - |
| 1 | WATER DRAIN HOSE (SN) | NECESSARY | 9.03 | 9.03 |
| 1 | HOOD LATCH SATIN BLACK LID LOCK (SN) | NOT NECESSARY | 332.14 | - |
| 1 | STRIKER PLATE (SN) | NOT NECESSARY | 59.94 | - |
| 1 | VW SIGN (SN) | NOT NECESSARY | 101.88 | - |

Report Ref No. CS/SMR22009920/Eqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1 | INSCRIPTION BRIGHT CHROME GOLF WORDING (SN) | NECESSARY | 86.75 | 86.75 |
| 1 | ADDITIONAL BRAKE LIGHT WI (SN) | NECESSARY | 183.08 | 183.08 |
| 1 | ADHESIVE REMOVER (SN) | NECESSARY | 120.29 | 120.29 |
| 1 | PRIMER (SN) | NECESSARY | 30.27 | 30.27 |
| 2 | APPLICATOR (SN) | NECESSARY | 22.32 | 22.32 |
| 1 | ACTIVATOR (SN) | NECESSARY | 26.27 | 26.27 |
| 1 | 1K WINDOW ADHESIVE (SN) | NECESSARY | 102.88 | 102.88 |
| 1 | REAR NUMBER PLATE (SN) | NOT NECESSARY | 80.00 | - |
| 1 | LIC. PLATE HOLDER (SN) (ADDITIONAL) | CUT | 35.72 | 35.72 |
| 1 | TRIM FOR TAIL LIGHT (SN) (ADDITIONAL) | CUT | 16.05 | 16.05 |
| 1 | ATTACHMENT STRIP RR BUMPER BRACKET (CTR) (SN) (ADDITIONAL) | BENT | 73.18 | 73.18 |
| 1 | BUMPER REINFORCEMENT (SN) (ADDITIONAL) | BENT | 750.84 | 750.84 |
| | | | 9,151.93 | 6,198.25 |
| | LABOUR | | | |
| | B&P CHECK SHORT CIRCUIT / HARNESS REPAIR. | | 280.00 | 280.00 |
| | B&P DIAGNOSIS AND PROGRAMMING. | | 480.00 | 480.00 |
| | LABOUR. | | 5,040.00 | 2,100.00 |
| | SPRAY PAINTING. | | 3,200.00 | 2,400.00 |
| | R&R REAR WINDSCREEN. | | 840.00 | 840.00 |
| | TRANSFER BOOT LID MECHANISM. | | 840.00 | 420.00 |
| | REAR WATER LEAK TEST. | | 150.00 | 150.00 |
| | | | 10,830.00 | 6,670.00 |
| | GRAND TOTAL | | 19,981.93 | 12,868.25 |
| | RECOMMENDED COST OF REPAIRS | | | 12,868.25 |

Report Ref No. CS/SMR22009920/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.