

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009926/APA3Q2**Date:** 27/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027067
Claimant Vehicle No :	SMD6446H	Insured Vehicle No :	SMY9046Z
Date of Loss:	05/10/2022	Nature of Claim:	TP
		Claim No:	0296585925SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6446H	Engine No:	DEM033948
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Chassis No:	WAUZZZF50MA059857
Reg. Date:	31/12/2021 (Man. Year: 2021)	Odometer:	12605 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30 R20	Rear Tyre Size:	265/30 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,850.00	1,564.80	8,285.20	84.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,172.00	1,722.00	1,450.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,022.00	3,286.80	9,735.20	74.76
+ GST 7.00/7.00% (S\$)	911.54	230.08	681.46	74.76
Nett Amount (S\$)	13,933.54	3,516.88	10,416.66	74.76
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,818.88		

INSPECTION

Date of Assignment:	06/10/2022		
Date Inspected:	06/10/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Repair	2,493.00 FS	*- FS	
2	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS	
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS	
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS	
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS	
6	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS	
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS	
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS	
9	2		*FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH	Not Necessary	108.00 FS	*- FS	
10	1		*RADIATOR GRILLE TRIM - CENTER	Not Necessary	127.00 FS	*- FS	
11	1		*RADIATOR GRILLE	Cracked	1,881.00 FS	*1,504.80 FS	
12	1		*RADIATOR GRILLE COVER	Not Necessary	141.00 FS	*- FS	
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS	
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS	
15	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS	
16	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS	
17	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS	
18	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS	
19	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS	
20	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS	
21	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	531.00 FS	*- FS	
22	4		*PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS	
23	1		*NOISE INSULATION	Not Necessary	640.00 FS	*- FS	
24	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS	
25	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS	
					Total Parts (S\$)	9,850.00	1,564.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
4	TO REAPPLY PAINT COATING FOR THE AFFECTED PANELS. (BY OWNER)	New	100.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,172.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >